



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

May 29, 2007

RE: NOTICE OF VIOLATION
FAILED ANNUAL STAGE II COMPLIANCE TEST
SPEEDWAY/SUPERAMERICA #3685
OHIO EPA ID #0243081012

CERTIFIED MAIL

Missy Stanaway
Speedway/SuperAmerica LLC
PO Box 1500
Springfield, OH 45501

Dear Ms. Stanaway:

The annual Stage II compliance test conducted at Speedway/SuperAmerica#3685 located at 7745 Reynolds Rd. in Mentor, Ohio 44060 on May 17, 2007, failed to demonstrate compliance for the following parameters:

<u>Parameter</u>	<u>Pass/Fail</u>
A/L Test	Failed
Pressure Decay Test	Failed
Dynamic Pressure Test	Not required this year
Ohio EPA Inspection	Passed

The pressure decay (static leak) test failed due to leaking seals around several vacuum motors. Also, the A/L tests were not completed on several dispensers.

Please have the necessary repairs completed and the failing equipment retested within three weeks of your receipt of this letter.

Failed test results constitute a violation of OAC Rule 3745-21-09 (DDD).

Violation of state air pollution control regulations are punishable by a civil penalty of \$25,000 per violation. Issuance of this notice does not excuse any violation of state law regarding air pollution.

Sincerely,

Dennis Bush
Environmental Manager
Division of Air Pollution Control

DB:bo

cc: Bob Prinicic, DAPC, NEDO
Tom Kaiman, DAPC, CO
Lisa Holscher, USEPA, Region V
Station Manager