



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

June 21, 2007

RE: NOTICE OF VIOLATION
FAILED ANNUAL STAGE II COMPLIANCE TEST
BP #22336
OHIO EPA ID #0247120954

CERTIFIED MAIL

Becky Stackhouse
BP Products North America
PO Box 6038
Artesia, CA 90702

Dear Ms. Stackhouse:

The annual Stage II compliance test conducted at BP ##22336 located at 5219 Detroit Rd. in Sheffield, Ohio 44035 on June 4, 2007, failed to demonstrate compliance for the following parameters:

<u>Parameter</u>	<u>Pass/Fail</u>
A/L Test	Passed
Static Leak Test	Failed
Dynamic Pressure Test	Not required this year
Ohio EPA Inspection	Passed

The inspector noted that the spill bucket was leaking on tank #2.

Failed test results constitute a violation of OAC Rule 3745-21-09 (DDD).

Please complete the necessary repairs and conduct a retest within three weeks of your receipt of this letter.

Violation of state air pollution control regulations are punishable by a civil penalty of \$25,000 per violation. Issuance of this notice does not excuse any violation of state law regarding air pollution.

Sincerely,

Dennis Bush
Environmental Manager
Division of Air Pollution Control

DB:bo

cc: Bob Prinic, DAPC, NEDO
Tom Kaiman, DAPC, CO
Lisa Holscher, USEPA, Region V
Station Manager