



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.  
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korteski, Director

July 29, 2008

RE: NOTICE OF VIOLATION  
FAILED ANNUAL STAGE II COMPLIANCE TEST  
SPEEDWAY/SUPERAMERICA #3529  
OHIO EPA ID #0243161046

CERTIFIED MAIL

Missy Stanaway  
Speedway/SuperAmerica LLC  
P.O. Box 1500, 207 Walter St.  
Springfield, OH 45501

Dear Ms. Stanaway:

The annual Stage II compliance test conducted at Speedway/SuperAmerica #3529 located at 34740 Lakeshore Blvd. in Willoughby, Ohio 44094 on July 24, 2008, failed to demonstrate compliance for the following parameters:

<u>Parameter</u>	<u>Pass/Fail</u>
A/L Test	Failed
Static Leak Test	Failed
Dynamic Pressure Test	Not required this year
Ohio EPA Inspection	Passed

The vacuum pumps for dispensers 8, 9, and 10 were leaking. This meant that the static leak test could not be done and these dispensers failed the A/L test. The other dispensers needed to be adjusted in order to pass the A/L test.

We have noted that this site also failed to comply initially during the compliance tests in 2006 and 2007.

Please schedule repairs and conduct a retest within 14 days of your receipt of this letter.

Failed test results constitute a violation of OAC Rule 3745-21-09 (DDD).

Violations of state air pollution control regulations are punishable by a civil penalty of \$25,000 per violation. Issuance of this notice does not excuse any violation of state law regarding air pollution. An enforcement action will be initiated if this site does not return to compliance within 14 days of your receipt of this letter.

Sincerely,

Dennis Bush  
Environmental Manager  
Division of Air Pollution Control

DB:bo

cc: Bob Princic, DAPC, NEDO  
Tom Kalman, DAPC, CO  
Lisa Holscher, USEPA, Region V  
Station Manager