



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.  
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

February 21, 2008

RE: NOTICE OF VIOLATION  
FAILED ANNUAL STAGE II COMPLIANCE TEST  
BP #86519  
OHIO EPA ID #0243161063

Becky Stackhouse  
BP Products North America  
PO Box 6038  
Artesia, CA 90702

**CERTIFIED MAIL**

Dear Ms. Stackhouse:

The annual Stage II compliance test conducted at BP #86519 located at 4015 Erie St. in Willoughby, Ohio 44094 on February 5, 2008 failed to demonstrate compliance for the following parameters:

<u>Parameter</u>	<u>Pass/Fail</u>
A/L Test	Failed on dispensers 3, 6, & 9
Static Leak Test	Failed
Dynamic Pressure Test	Not required this year
Ohio EPA Inspection	Passed

We have noted that this site has failed for five years in a row on the initial attempt at demonstrating compliance. Proper maintenance of the Stage II vapor control equipment will prevent these failures and reduce gasoline vapors being emitted into the environment.

Please schedule repairs and conduct a retest within 14 days of your receipt of this letter.

Failed test results constitute a violation of OAC Rule 3745-21-09 (DDD).

Violation of state air pollution control regulations are punishable by a civil penalty of \$25,000 per violation. Issuance of this notice does not excuse any violation of state law regarding air pollution. An enforcement action will be initiated if this site does not return to compliance within 14 days of your receipt of this letter.

Sincerely,

Dennis Bush  
Environmental Manager  
Division of Air Pollution Control

DB:bo

cc: Bob Prinic, DAPC, NEDO  
Tom Kalman, DAPC, CO  
Lisa Holscher, USEPA, Region V  
Station Manager