



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

March 4, 2008

RE: FAILED ANNUAL STAGE II COMPLIANCE TEST
BP #22338
OHIO EPA ID #0247090960

NOTICE OF VIOLATION

CERTIFIED MAIL

Ms. Becky Stackhouse
BP Products North America
PO Box 6038
Artesia, CA 90702

Dear Ms. Stackhouse:

The annual Stage II compliance test conducted at BP #22338 located at 32390 Lorain Road in North Ridgeville, Ohio 44039 on February 19, 2008 failed to demonstrate compliance for the following parameters:

| <u>Parameter</u> | <u>Pass/Fail</u> |
|-----------------------|-----------------------------------|
| A/L Test | Failed on dispensers 4,5,6,7,8,11 |
| Static Leak Test | Passed |
| Dynamic Pressure Test | Not required this year |
| Ohio EPA Inspection | Passed |

Please schedule repairs and conduct a retest within 14 days of your receipt of this letter.

Failed test results constitute a violation of OAC Rule 3745-21-09 (DDD).

Violations of state air pollution control regulations are punishable by a civil penalty of \$25,000 per violation. Issuance of this notice does not excuse any violation of state law regarding air pollution. An enforcement action will be initiated if this site does not return to compliance within 14 days of your receipt of this letter.

Sincerely,

Dennis Bush
Environmental Manager
Division of Air Pollution Control

DB/mt

cc: Bob Princic, Ohio EPA, DAPC, NEDO
Tom Kalman, Ohio EPA, DAPC, CO
Lisa Holscher, U.S. EPA, Region V
Station Manager