




18513 Euclid Avenue
Cleveland, Ohio 44112-1084
216-486-1313
Fax 216-486-1321
www.meyerproducts.com
E-mail info@meyerproducts.com

June 27, 2008

George Baker
Chief of Enforcement
Cleveland Department of Public Health
Division of Air Quality
1925 St. Clair Avenue NE
Cleveland, Ohio 44114



Subject: Response to Receipt of Corrective Action For Meyer Products, Facility Number
13-18-00-1982 Dated June 11, 2008

Dear Mr. Baker,

Thank you for your letter on June 11, 2008 confirming your receipt of our corrective actions letter dated May 28, 2008. In your letter, you detailed several areas where our corrective actions either require more detail or, in some cases, needed to be revised. Meyer Products thanks you for bringing this to our attention. We have addressed all of these issues in the following paragraphs and attachments.

Attached to this letter are revised quarterly and semi-annual deviation reports for units L001, P006, P008 and Z004. These revised reports cover those time periods where the CDAQ investigation discovered deviations from our specified term and conditions for equipment operation.


As stated in our May 28, 2008 letter, corrective actions were taken on L001 prior to May 30th. Meyer's HVAC contractor repaired a leak and recharged the system with refrigerant. These initial actions reduced the temperature to below the specified -10° F maximum as described in our permit. This favorable operating condition however was very short lived. After only running this equipment four (4) times in the month of June, the temperature has raised to 0° F. Several phone calls have been placed to the original equipment manufacturer (OEM) to help diagnose a cost efficient repair. We hope to have a viable solution by mid-July. I will inform your office personally when this unit is repaired.

Repairs on P008 Laser Dust Collector, on the other hand, have been extremely successful. A new controller was installed on June 23, 2008. This new controller has the features, sensitivity and powered down memory that allows this equipment to function reliably between 4" and 6" of water. A copy of the repair work order has been included for your reference. For your reference, Meyer's original estimated completion date for this repair was August 15, 2008.

Please feel free to contact me directly should you have any questions about this letter or any of its contents.

Sincerely,

MEYER PRODUCTS

A handwritten signature in black ink that reads "Michael Javaras". The signature is written in a cursive style with a large, prominent initial "M".

Michael Javaras
Director of Operations

cc: Andy Outcalt, Meyer Products
Paul Jack, Castle Bay Inc.

The logo for Meyer, featuring the word "Meyer" in a bold, sans-serif font. The letter "y" has a distinctive shape with a horizontal bar at its base. A registered trademark symbol (®) is located to the upper right of the word.

A Subsidiary of The Louis Berkman Work Products Company
Meyer * Swenson