



**CLE** CLEVELAND HOPKINS  
INTERNATIONAL AIRPORT

**BKL** CLEVELAND BURKE  
LAKEFRONT AIRPORT

June 2, 2010

Bryan Sokolowski  
Environmental Enforcement Specialist I  
Cleveland Department of Public Health  
Division of Air Quality  
75 Erieview Plaza 2nd Floor  
Cleveland, Ohio, 44114

RECEIVED

JUN - 8 2010

**RE: Timeframe to Correct Alleged Violations**  
**Facility ID: 13-18-00-4181**

Dear Mr. Sokolowski:

On March 4, 2010, the Cleveland Division of Air Quality (CDAQ) was on-site to complete an inspection at Cleveland Hopkins International Airport (CLE) for our boilers, emergency generators, gas dispensing and the incinerator. CDAQ advised our Environmental Services section that they needed to update their files of any air contaminant sources at CLE, and was escorted by representatives from Environmental Services and the Electrical Division throughout the Airport facilities. Although several of the operating sources presently on-site were installed and permitted correctly over the past decade, the below mentioned new installations have been determined by CDAQ to be operating in violation of air statues, regulations and/or air permitting conditions:

1. One (1) Incinerator: Failure to submit a Permit-to-Operate (PTO) Renewal Application for Emission Unit (EU) N001
2. Four (4) recently-installed Electrical Generators: Failure to submit a permit application
3. Several additional units or installations: Failure to obtain all 2006-2009 City Permits-to-Operate

Corrective actions have been identified and will commence with the current cumulative Notice of Violation, so that compliance can be obtained for Ohio Administrative Code (OAC) 3745-31 Permit-to Install New sources and Permit-to-Install and Operate Program and Ohio Revised Code (ORC) 3704 Air Pollution Control, as well as City of Cleveland Codified Ordinance Chapters 259.01 and

Cleveland Hopkins International Airport  
5300 Riverside Drive  
P.O. Box 81009  
Cleveland, OH 44181-0009  
USA  
1 216 265 6800


Cleveland Burke Lakefront Airport  
1501 North Marginal Road  
Cleveland, OH 44114-3759  
1 216 781 6411

263.01 for failing to obtain all 2006-09 city permits-to-operate by not submitting city permit fees. Department of Port Control is currently in progress of completing the abovementioned corrective actions; however request a time extension past the 30 day response timeframe. The timeline for the corrective actions is proposed in the table below.

Corrective Actions	Proposed timeline
Complete a Permit to Operate (PTO) renewal for the Incinerator	June 30, 2010
Complete PTIOs (or Permit by Rule) for four (4) new emergency generators	June 30, 2010
Process payment for the retroactive amount for the 2006-2009 PTOs (total of \$4,087.50)	June 23, 2010

In advance, thank you for your cooperation.

Sincerely,



Steve Nagy  
Chief of Planning and Engineering

SN/km

Cc: Ricky D. Smith, Director of Airports  
Fred Szabo, Commissioner  
Kim McGreal, Environmental Services Manager