

Computer  
Copy

April 21, 2010

WARNING LETTER

Bill Rupert  
BP-Husky Refining LLC.  
P.O. Box 696  
Toledo, Ohio 43697-0696


Re: CEMS Excessive Downtime

Dear Mr. Rupert:

This letter is in regards to the fourth quarter of 2009 report submitted on January 21, 2010, for H<sub>2</sub>S Continuous Emissions Monitoring Systems (CEMS) which monitors the Reformer 1 Furnace (B014) and SO<sub>2</sub> CEMS which monitors Fluidized Catalytic Cracking Unit/CO Boiler (P007). The report indicates that the percent of CEMS downtime was greater than 5 % of the total operating time during the reported quarter.

Please be aware that future quarters of excess emissions/CEMS downtime may result in a Notice of Violation.

If you have any questions, please feel free to contact me at 419-936-3936.

Sincerely,  
  
Peter Park  
Engineer

cc: Karen Granata  
Leslie A. Kovacik, City of Toledo  
John Paulian, Ohio EPA  
Lisa Holscher, US EPA b