



AKRON REGIONAL AIR QUALITY MANAGEMENT DISTRICT

Agent of the Ohio Environmental Protection Agency • Division of the Akron Health Department
Serving Medina, Portage and Summit Counties

TELEPHONE: (330) 375-2480
FAX: (330) 375-2402

L. M. Malcolm, P.E.
Administrator

May 27, 2011

Ms. Teri Smith
Speedway SuperAmerica, LLC
PO Box 1500
Springfield, OH 45501

Dear Ms. Smith:

A representative of the Akron Regional Air Quality Management District (ARAQMD) inspected the following Speedway SuperAmerica gasoline dispensing facilities to determine compliance with OAC 3745-21-09 (DDD) regarding Stage II vapor recovery:

<u>Date</u>	<u>Site</u>	<u>Address</u>	<u>City</u>
1/14/11	3661	317 E. Highland Rd. 1677 080030	Macedonia
1/19/11	3672	5211 Manchester Rd. 1677 000542	Akron
1/24/11	9715	390 E. Exchange St. 1677 010888	Akron
1/27/11	3999	3220 Center Rd. 1652 010026	Brunswick
1/27/11	3390	9254 SR 43 1667 080020	Streetsboro
1/28/11	3686	4969 Fishcreek Rd. 1677 110041	Stow
2/8/11	3635	3903 Mogadore Rd. 1677 150023	Mogadore
2/22/11	3636	9 N. Cleveland Massillon Rd.	Akron 1677 000157
2/25/11	3634	293 E. Market St. 1677 011154	Akron
3/7/11	3673	3021 S. Arlington St. 1677 000543	Akron
3/9/11	3681	765 Darrow Rd. 1677 010832	Akron
3/25/11	1168	900 N. Court St. 1652 030008	Medina
3/30/11	3505	10769 North St. 1667 030017	Garrettsville

Inspection results/Deficiencies:

<u>Station</u>	<u>Deficiency</u>
3999	This facility was formerly Marathon #3116. Please submit PBR Notification Form to document transfer of ownership. Also establish record keeping file at station.

CITICENTER - SUITE 904

146 SOUTH HIGH STREET • AKRON, OHIO 44308


An equal opportunity employer and provider of services - CRA 1964

<u>Station</u>	<u>Deficiency</u>
3390	Equipment: This facility failed Stage II testing on 1/27/11. Repair and retesting are to be completed within 30 days.
3636	Record keeping: A Certificate of Stage II training was missing from station file.
3673	ARAQMD file: A review of our records found that the results of Stage II testing completed on 3/7/11 have not been submitted. Speedway SuperAmerica is in violation of OAC 3745-21-09(DDD)(2)(c) which requires the results of testing be submitted within 30 days of tests completion.
3681	ARAQMD file: A review of our records found that the results of Stage II testing completed on 3/9/11 have not been submitted. Speedway SuperAmerica is in violation of OAC 3745-21-09(DDD)(2)(c) which requires the results of testing be submitted within 30 days of tests completion.
3505	ARAQMD file: A review of our records found that the results of Stage II testing completed on 3/30/11 have not been submitted. Speedway SuperAmerica is in violation of OAC 3745-21-09(DDD)(2)(c) which requires the results of testing be submitted within 30 days of tests completion.

These facilities will be inspected on an annual basis for compliance with the Stage II vapor recovery rule. It is required that you keep record keeping information at a readily available location for inspection. For this Agency, it is requested that you keep copies of the required information at each individual location where all employees can access them.

Thank you for your cooperation and assistance in this matter. If you have any questions, please contact me at 330/375-2480 x4255.

Sincerely,



Steven Stakleff, RS
Sanitarian II