

AKRON REGIONAL
AIR QUALITY MANAGEMENT DISTRICT

Agent of the Ohio Environmental Protection Agency • Division of the Akron Health Department
Serving Medina, Portage and Summit Counties

TELEPHONE: (330) 375-2480
FAX: (330) 375-2402

L. M. Malcolm, P.E.
Administrator

August 1, 2008

Mr. Sarjit Heera
Hayer Corp. dba Lo-Boy Gasoline
6171 Manchester Road
Akron, OH 44319

Dear Mr. Heera:

A representative of the Akron Regional Air Quality Management District (ARAQMD) inspected the following Hayer Corp. Lo Boy Oil gasoline dispensing facilities to determine compliance with OAC 3745-21-09 (DDD) regarding Stage II vapor recovery:

<u>Date</u>	<u>Site</u>	<u>Address</u>	<u>City</u>
7/30/08	Barberton	134 Tuscarawas Road	Barberton 1677 020135
7/30/08	Akron	6171 Manchester Road	Akron 1671 000550

Inspection results/Deficiencies:

<u>Site</u>	<u>Deficiency</u>
Barberton	Record keeping: The Ohio EPA Permit to Operate on file for this facility has expired.
	ARAQMD file: A review of our records found the Ohio EPA Permit to Operate for this facility expired on 6/20/2008. Ohio Administrative Code 3745-35-02 requires issuance of a Permit to Operate (PTO) before any air contaminant source can be operated. Ohio Revised Code section 3704.05 prohibits any violation of the Ohio Environmental Protection Agency (Ohio EPA) regulations and provides for civil and criminal penalties for violations. Permit renewal forms have been enclosed with this notification of violation.

CITICENTER - SUITE 904
146 SOUTH HIGH STREET • AKRON, OHIO 44308
An equal opportunity employer and provider of services - CRA 1964

Mr. Sarjit Heera
Page 2
August 1, 2008

<u>Site</u>	<u>Deficiency</u>
Akron	<p>Record keeping: The Ohio EPA Permit to Operate, results of Stage II testing and post test inspection forms for 2005, 2006, & 2007 were missing from the Station file.</p> <p>ARAQMD file: A review of our records found the Ohio EPA Permit to Operate for this facility expired on 6/25/2008. Ohio Administrative Code 3745-35-02, requires issuance of a Permit to Operate (PTO) before any air contaminant source can be operated. Ohio Revised Code section 3704.05 prohibits any violation of the Ohio Environmental Protection Agency (Ohio EPA) regulations, and provides for civil and criminal penalties for violations Permit renewal forms have been enclosed with this notification of violation.</p>

Please correct the deficiencies noted. Within 14 days of receipt of this letter, Hayer Corp. is to submit a renewal application for the expired Ohio EPA Permits to Operate for these facilities.

This facility will be inspected on an annual basis for compliance with the Stage II vapor recovery rule. It is required that you keep record keeping information at a readily available location for inspection. For this Agency, it is requested that you keep copies of the required information at each individual location where all employees can access them.

Thank you for your cooperation and assistance in this matter. If you have any questions, please contact me at 330/375-2480 x4255.

Sincerely,



Steven Stakleff, RS
ARAQMD Sanitarian II

SA
Enclosures