

Correspond.



State of Ohio Environmental Protection Agency

Southwest District

401 East Fifth Street
Dayton, Ohio 45402-2911

TELE: (937)285-6357 FAX: (937)285-6249
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lt. Governor
Chris Korleski, Director

April 5, 2007

Mr. Ralph Goubeaux
Facility Manager, DMAX-LTD
3100 Dryden Rd.
Moraine, Ohio 45439

Re: Response to DMAX letter of March 28, 2007
DMAX, Ltd. , OHR000038422, LQG, Montgomery County

Dear Mr. Goubeaux,

Ohio EPA is in receipt of DMAX-Ltd.'s March 28, 2007 letter responding to Ohio EPA's March 22, 2007 letter. Mark Helke's response includes the results of analysis from a sample taken from the CB 140 tank 2 clean out of November 9, 2006. The sample was analyzed for corrosivity, ignitability, TCLP metals, and VOC (totals). Note that Ohio EPA recommends a sample should be analyzed for all constituents on the TCLP list, not just metals. The results of analysis indicate that the November 9, 2006 clean out is not a hazardous waste.

As noted in DMAX's December 19, 2006 letter DMAX should continue to sample and analyze several batches of this waste stream in order to determine if it is consistently hazardous or not. Based upon our review of available results, each batch of waste should be sampled and analyzed for ignitability and all TCLP constituents (including both metals & VOCs). Continue to submit the results of analysis to this office. With each submittal, please include the work order associated with the clean out which documents the date of the clean out. Samples should be taken at the end of life cycle.

Ohio EPA's failure to list specific deficiencies or violations in this letter does not preclude DMAX from having to comply with all applicable regulations. If you have further questions, please feel free to call me at (937) 285-6082.

Sincerely,

Brian Gitzinger
District Representative
Division of Hazardous Waste Management

cc: Dinah Crawford, DHWM, SWDO
~~Tom Koch, DHWM, SWDO~~

BG/plh

