



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

July 23, 2009

**RE: ETCHED METAL COMPANY
OHD 004 153 599
CUYAHOGA COUNTY
LQG CEI RTC**

Michael McDivitt
Etched Metal Company
30200 Solon Industrial Parkway
Solon, OH 44139

Dear Mr. McDivitt:

On June 17, 2009, I received your letter which responded to the violations and concern found during the February 26, 2009 hazardous waste inspection. As outlined below, you documented a correction of all the issues found.

1. OAC rule 3745-273-13 (D) - Universal waste lamp containers.
This was corrected during the inspection.
2. OAC rule 3745-65-52(E) – Contingency plan emergency equipment.
3. OAC rule 3745-65-33 – Testing and maintenance of equipment.
4. OAC rule 3745-66-76 – Special requirements for ignitable or reactive waste.
5. Concrete blocks stored outside that appeared to be contaminated.
Your letter shows that these three violations have been corrected since the inspection and that the one concern was properly addressed.

If you have any questions, please contact me at (330) 963-1217, or robert.almquist@epa.state.oh.us.

Sincerely,

Robert Almquist
Division of Hazardous Waste Management

RA:cl

ec: Frank Popotnik, DHWM, NEDO cc: Natalie Oryshkewych, DHWM, NEDO
Harry Sarvis, DHWM, CO
Sherry Slone, DHWM, NEDO
Valarie Mariola, Etched Metal Company
Jeffrey Thompson, Etched Metal Company

Notice:

Ohio EPA's failure to list specific deficiencies or violations in this letter does not relieve your facility from its obligation to comply with all applicable regulations.