



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

June 11, 2008

Ed Deditch
Plant Manager
1530 E. 40th St.
Cleveland, OH 44103

**RE: PRINCE PLATING, INC., OHD 004 165 429, CUYAHOGA COUNTY, RCRA/LQG
COMPLIANCE EVALUATION INSPECTION, RETURN TO COMPLIANCE**

Dear Mr. Deditch:

Thank you for your May 6, 2008 response to Ohio EPA's April 18, 2008 Notice of Violation (NOV) letter. You submitted information and documentation, including:

- Three (3) photographs of the new emergency communication device (telephone) recently installed adjacent to the hazardous waste accumulation area.
- A copy of the new inspection log sheet with the emergency communication device added.
- A copy of the facility's updated emergency response contingency plan dated April 25, 2008.
- A copy of the job titles and descriptions for each position at the facility which manages hazardous waste.
- A list of employees which manage hazardous waste in the form of a sign in sheet for hazardous waste training performed on March 18, 2008.
- Documentation demonstrating that the person performing the hazardous waste training, Ed Alkhatib, has been trained in hazardous waste management.
- A copy of analytical data and chain of custody for the following waste streams:
 - The buff washer water/sludge sampled on March 14, 2008.
 - The buff house dust sampled on March 14, 2008.
 - Paint spray booth coating sampled on March 14, 2008.
 - The alkaline pit sludge sampled on April 16, 2007.
- A copy of manifest # 003458358 JJK.
- Land Disposal Restriction forms for the D007 hazardous waste which was shipped on manifest # 000353259 JJK.
- A copy of a fax from Safety Kleen dated April 2, 2008, demonstrating that the facility's generator status has been corrected in their files.
- A copy of an incident report regarding the spill and subsequent clean up of F006 from the roll off box.

PRINCE PLATING, INC.
JUNE 11, 2008
PAGE – 2 –

- Copies of the following signed manifests from Agmet Metals:
 - #000353427 JJK dated December 28, 2007.
 - #003447268 JJK dated December 13, 2007.
 - #003447371 JJK dated November 16, 2007.
- Information and clarification regarding the 029L waste code observed on a shipment to Michigan Disposal.
- Copies of corrected LDR's and manifests sent to Safety Kleen and Agmet Metals for their files.

My review of this documentation reveals that PPI has adequately demonstrated abatement of the following hazardous waste violations cited in Ohio EPA's April 18, 2008 NOV letter and is hereby returned to compliance:

OAC 3745-65-32 Required equipment

OAC 3745-65-33 Testing and maintenance of equipment


OAC 3745-65-52(E) Content of contingency plan

OAC 3745-65-16 Personnel training

Failure to list specific deficiencies in this communication does not relieve PPI from the responsibility of complying with all applicable hazardous waste regulations. This letter does not relieve PPI from liability for any past or present violations of the state's hazardous waste laws.

Should you have any questions, please feel free to call me at (330) 963-1181.

Sincerely,



Suzanne Prusnek
Environmental Specialist
Division of Hazardous Waste Management

SP:ddw

cc: Natalie Oryshkewych, DHWM, NEDO, OEPA
Frank Popotnik, DHWM, NEDO, OEPA
Harry Sarvis, DHWM, CO, OEPA