



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

June 22, 2009

RE: ROSS INCINERATION SERVICES, INC.
OHD 048 415 665
OHIO ID# 02-47-0295
NOTICE OF VIOLATION (NOV)
RETURN TO COMPLIANCE (RTC)

Ms. Deborah A. Bishop
Environmental Compliance Supervisor
Ross Incineration Services, Inc.
36790 Giles Road
Grafton, OH 44044

Dear Ms. Bishop:

On March 19, 2009 Ohio EPA received a letter dated March 16, 2009 from Ross Incineration Services Inc. (RIS) in which RIS voluntarily disclosed an instance of noncompliance with a permit condition pursuant to Permit Condition A.22, specifically:

- Operators failed to complete the visual inspection of the Main Chamber Direct Feed Lances as required in Section F-2b(5) of the RIS Permit Application starting on 6:00 a.m. on February 10, 2009 through 5:00 a.m. on February 11, 2009.

The letter also noted that RIS took the following steps to abate the violation and to prevent reoccurrence:

- Immediate actions were taken to assure that operators completed the visual inspections.
- Operating procedures were reviewed with all incinerator operators.

Based on the information provided, adequate steps were taken to abate the above violation.

Should you have any questions regarding this letter, please contact me at (330) 963-1165.

Sincerely,

Neil Wasilk
Environmental Specialist II
Division of Hazardous Waste Management

NW:ddw

ec: Nyall McKenna, DHWM, NEDO
John Paquelet, DHWM, NEDO

NOTICE:

Ohio EPA's failure to list specific deficiencies or violations in this letter does not relieve your facility from its obligation to comply with all applicable regulations.