



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

February 12, 2007

**RE: LAWRENCE COUNTY
FAC - SCARBERRY & SON DEMOLITION, INC.
CONSTRUCTION AND DEMOLITION LANDFILL
ID # 44-00-04**

Ms. Alta Scarberry
Scarberry and Son Demolition, Inc.
6508 Little Seven Mile
Huntington W. Va. 25702-9762

Dear Ms. Scarberry:

On February 8, 2007, I conducted an inspection of Scarberry & Son construction and demolition debris landfill that is located in Proctorville, Ohio to determine the compliance with Ohio Administrative Code (OAC) 3745-400-11. During this inspection, I met with Rex Scarberry to discuss the operation of the landfill.

I have the following comments concerning the inspection:

I observed that the most recent demolition projects that have been taken to the landfill have not been spread evenly, were cliffed, and not covered with soil, this results in violations of OAC Rules 3745-400.

OAC Rule 3745-400-11(F)(c) Once prohibited materials are removed, the owner or operator shall spread and compact the debris on the working face. When debris is deposited on the working face, it shall be spread evenly over the working face and compacted to the smallest practical volume.

The debris has been cliffed over the edge and has not been spread and compacted. This is a violation.

OAC Rule 3745-400-11(F)(d) Clipping is prohibited, for the purpose of this rule clipping is the formation of an edge or cliff by the placement of debris to the working face without compacting.

The debris from the current demolition jobs has been cliffed and not compacted this is a violation.

OAC 3745-400-(H)(1) The owner or operator shall operate the facility in a manner that prevents fires by doing one of the following: Covering all disposed combustible debris on a weekly basis with soil, clean hard fill, or other material which is noncombustible. Covering means to apply noncombustible material in a manner such that combustible debris is not visible.

I also observed a crack in the landfill at the top of the landfill. This should be filled in with soil and compacted. This will help prevent water from infiltrating the landfill and causing additional problems such as slope stability issues.

OAC 3745-400-11(Q)(2) The owner or operator shall grade the facility and provide drainage systems to insure minimal infiltration of water through the cover material and cap system as well erosion of the cover material and cap system.

Please correct the above mentioned violations and contact me when these are corrected.

I also observed that you are recycling steel from the recycling area on this inspection.

If you have any questions, feel free to contact me at this District Office at 740-380-5246.

Sincerely,



Clint Shuff
Environmental Specialist, R.S.
Division of Solid and Infectious Waste Management

CS/jg

cc: Dan Palmer, Lawrence and Scioto County Solid Waste Management District
cc: Lawrence County Health Department