



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Lazarus Government Center  
50 W Town Street, Suite 700  
Columbus, OH 43215

MAILING ADDRESS:

Government Center  
P.O. Box 1049  
Columbus, OH 43216-1049

TELEPHONE: (614) 644-2752  
OH3001212 BYESVILLE 2456 27 03/02/09

March 2, 2009



BYESVILLE, VLG. OF  
221 MAIN ST  
PO BOX 8  
BYESVILLE, OH 43723

Re: GUERNSEY COUNTY  
BYESVILLE, VILLAGE OF  
Community Water System  
PWS ID: OH3001212

**NOTICE OF VIOLATION - ACTION REQUIRED**

**Subject: Failure to Monitor Drinking Water**

Byesville, Village Of is in violation of Ohio Administrative Code Rule 3745-81-24 for failing to monitor your drinking water during the October 1, 2008 to December 31, 2008 monitoring period and/or report results for the following contaminants: TOTAL HALOACETIC ACIDS (HAA5)

**In order to return to compliance,** Byesville, Village Of must take the following actions:

1. Immediately collect a sample of your drinking water from the maximum residence time (location in system where age of water is oldest).
2. Submit the sample for analysis to a certified laboratory on the enclosed list.
3. Notify your customers using the enclosed instructions and public notice.
4. Complete and return the enclosed verification form to this office.

Your prompt attention to this matter is greatly appreciated. Continued noncompliance may lead to enforcement actions. If you have any questions or if the required sample was tested, please call me at (614) 644-2752.

Sincerely,

Sarah Byerly  
Division of Drinking and Ground Waters

Enclosure: Public Notice; Public Notice Instructions and Verification Form; Laboratory List  
cc: Superintendent/Manager; DDAGW-SEDO file; DDAGW-CO file

# DRINKING WATER NOTICE

## Monitoring requirements not met for Byesville, Village Of

We are required to monitor your drinking water for specific contaminants on a regular basis. Results of regular monitoring are an indicator of whether or not our drinking water meets health standards. During the October 1, 2008 to December 31, 2008 time period we did not monitor for the following contaminants and therefore cannot be sure of the quality of our drinking water during that time: TOTAL HALOACETIC ACIDS (HAA5).

### **What Should I Do?**

This notice is to inform you that Byesville, Village Of did not monitor and report results for the presence of the contaminants listed above in the public drinking water system during the October 1, 2008 to December 31, 2008 time period, as required by the Ohio Environmental Protection Agency. You do not need to take any actions in response to this notice.

### **What Is Being Done?**

Upon being notified of this violation, the water supply was required to have the drinking water analyzed for the above mentioned parameters. The water supplier will take steps to ensure that adequate monitoring will be performed in the future.

Additional information may be obtained by contacting Byesville, Village Of at:

Contact Person: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Mailing Address: \_\_\_\_\_

*Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail*

PWSID: OH3001212

Date Distributed: \_\_\_\_\_