



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Central District Office

MAILING ADDRESS:

Lazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

P.O. Box 1049
Columbus, OH 43216-1049

December 4, 2007

Re: Pickaway County
Village of Darbyville
Community Water System
PWS ID: 6503412

Village Council
Village of Darbyville
16671 Main Street
Williamsport, OH 43164

Dear Council:

In accordance with Ohio Administrative Code (OAC) Rule 3745-83-01(C)(1), community water systems are required to maintain a minimum chlorine residual of at least 0.2 mg/L free or 1.0 mg/L combined chlorine throughout the distribution system. OAC Rule 3745-83-01(G)(1) & (2) requires the public water system owner to monitor for free and combined chlorine residuals at least once every day. According to the Village's October 2007 monthly operating report, the chlorine residuals were below the minimum levels within the distribution system for 16 days during the month. The Village was issued a violation last month for this same scenario in September 2007. This practice of not maintaining adequate chlorine residuals is unacceptable.

Within 14 days you are required to submit in writing a plan of action to ensure that proper chlorine residuals are maintained within the Village's distribution system. If you have any questions, please call me at (614) 728-3870.

Sincerely,

Bridgette Marchio
Environmental Specialist
Division of Drinking and Ground Waters
Central District Office

c: Bill Eitel, Water Specialists, Inc.
Pickaway County Health Department
CDO File

BM/ct darbyvilleNovember2007

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director