



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Lazarus Government Center  
50 W Town Street, Suite 700  
Columbus, OH 43215

TELE: (614) 644-2752 F:  
www.epa.stat

OH5244412 SKYPARK AIRPORT CLUBHOUSE CNO3 MR 12/01/10



\* 0 H 5 2 4 4 4 1 2 4 8 8 4 \*

December 1, 2010

SKYPARK AIRPORT  
3071 GREENWICH ROAD  
WADSWORTH, OH 44281

Re: MEDINA COUNTY  
SKYPARK AIRPORT CLUBHOUSE PWS  
Transient Noncommunity Water System  
PWS ID: OH5244412  
STU ID: 5260934

**DELINQUENCY NOTICE - ACTION REQUIRED**

**Subject: Failure to Monitor Drinking Water**

SKYPARK AIRPORT CLUBHOUSE PWS is in violation of Ohio Administrative Code Rule 3745-81-23 for failing to monitor your drinking water during the June 1, 2010 to October 31, 2010 monitoring period and/or report results for the following contaminants: NITRATE (AS N).

SKYPARK AIRPORT CLUBHOUSE PWS must promptly take the following actions.

- A. If sample was taken during this monitoring period,
  - a. Call your laboratory and have them submit the results to Ohio EPA.
  - b. Contact this office at (614) 644-2752 to consult with us on this issue.

- OR -
- B. If sample was not taken during or after this monitoring period,
  - a. Immediately take a sample of your drinking water from the first tap following treatment.
  - b. Submit the sample for analysis to a certified laboratory on the enclosed list.

- OR -
- C. If sample was taken after this monitoring period, contact this office at (614) 644-2752.

Your prompt attention to this matter is appreciated. Continued failure to sample during your scheduled time period may lead to enforcement which may include penalties. If you have questions, please call me at (614) 644-2752.

Sincerely,

Wendy Sheeran  
Division of Drinking and Ground Waters

Enclosure: Laboratory List

cc: Superintendent/Manager; DDAGW-NEDO file; DDAGW-CO file

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

