

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:



MR H RANK WOOLARD
 GENERAL ELECTRIC AIRCRAFT EN
 1 NEUMANN WAY N123
 CINCINNATI OH 45215

2. Article Number
 (Transfer from service label)

PS Form 3811, August 2001

COMPLETE THIS SECTION ON DELIVERY

A. Signature

X *[Handwritten Signature]*

 Agent Addressee

B. Received by (Printed Name)

[Handwritten Name]

C. Date of Delivery

D. Is delivery address different from item 1? YesIf YES, enter delivery address below: No

3. Service Type

 Certified Mail Express Mail Registered Return Receipt for Merchandise Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee)

7005 0390 0004 9401 6581

Domestic Return Receipt

02595-02-M-1540

UNITED STATES POSTAL SERVICE




First-Class Mail
Postage & Fees Paid
USPS
Permit No. G-10

• Sender: Please print your name, address, and ZIP+4 in this box •



OHIO EPA-SWDO
MARIANNE PIEKUTOWSKI
401 EAST FIFTH STREET
DAYTON OH 45402 2911



7005 0390 0004 9401 6581

U.S. Postal Service™
CERTIFIED MAIL™ RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com

OFFICIAL USE

Postage	\$
Certified Fee	
Return Receipt Fee (Endorsement Required)	
Restricted Delivery Fee (Endorsement Required)	
Total Postage & Fees	\$

Mailed
12-5-07
Postmark
Here
Marianne
P.

Sent To
 General Electric Aircraft Engines
 Street, Apt. No.,
 or PO Box No. Neuman Way 1123
 City, State, ZIP+4 Cincinnati OH 45215

See Reverse for Instructions

Certified Mail Provides:

- A mailing label
- A unique identifier for your mailpiece
- A record of delivery kept by the Postal Service for two years

PS Form 3800, June 2002 (Reverse)

Important Reminders:

- Certified Mail may ONLY be combined with First-Class Mail® or Priority Mail®.
- Certified Mail is not available for any class of international mail.
- NO INSURANCE COVERAGE IS PROVIDED with Certified Mail. For valuables, please consider Insured or Registered Mail.
- For an additional fee, a *Return Receipt* may be requested to provide proof of delivery. To obtain Return Receipt service, please complete and attach a Return Receipt (PS Form 3811) to the article and add applicable postage to cover the fee. Endorse mailpiece "Return Receipt Requested". To receive a fee waiver for a duplicate return receipt, a USPS® postmark on your Certified Mail receipt is required.
- For an additional fee, delivery may be restricted to the addressee or addressee's authorized agent. Advise the clerk or mark the mailpiece with the endorsement "*Restricted Delivery*".
- If a postmark on the Certified Mail receipt is desired, please present the article at the post office for postmarking. If a postmark on the Certified Mail receipt is not needed, detach and affix label with postage and mail.

IMPORTANT: Save this receipt and present it when making an inquiry. Internet access to delivery information is not available on mail addressed to APOs and FPOs.



State of Ohio Environmental Protection Agency
Southwest District

401 East Fifth Street
Dayton, Ohio 45402-2911

TELE: (937)285-6357 FAX: (937)285-6249
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lt. Governor
Chris Korleski, Director

December 4, 2007

Mr. H. Frank Woolard
General Electric Aircraft Engines
1 Neumann Way, N123
Cincinnati, Ohio 45215

Re: Hamilton County - General Electric Aircraft Engines -
OH0010286;1IN00006*GD - NOTICE OF VIOLATION

CERTIFIED MAIL

Dear Mr. Woolard:

This office has received the non-compliance notification for the above referenced facility. Our review indicates violations of the conditions of your NPDES permit. The specific instances of non-compliance and/or deficiencies were as follows:

EFFLUENT LIMIT VIOLATIONS

Station No. 1IN00006001

<i>Parameter</i>	<i>Code</i>	<i>Date</i>	<i>Reported</i>	<i>Units</i>	<i>Permit Limit</i>
Temperature	00010	09/24/2007	30	°C	29 °C

In addition, there were two unauthorized discharges to the Mill Creek. On October 1, 2007, an unauthorized discharge of sanitary wastewater entered into the storm sewer that discharges to Mill Creek. At approximately 7:45 am, an underground sanitary sewer had ruptured, and had begun to discharge wastewater over ground into a grassy area. Some of the wastewater eventually reached a storm drain that flows to the facility's outfall and then into Mill Creek. Upon discovery, the pumps to the sanitary sewer were shutdown so no additional flow would be released. It is estimated that 50 gallons of sanitary wastewater were discharged through the NPDES outfall.

The second release was on November 10, 2007. A contractor working at the facility accidentally cut both an underground domestic water line as well as a salt brine line that feeds the water softening treatment buildings. Before contacting any of the facility personnel, the contractor began pumping the mixture out to the on-site drainage ditch to



December 4, 2007

Page 2

get to the lines to cap them. It is estimated that approximately 100 gallons of brine were pumped into the ditch and mixed with the non-contact cooling water before it reached the permitted outfall.

Please be advised that failure to comply with the effluent limitations, or to satisfy monitoring or reporting requirements of your NPDES permit may be cause for enforcement action pursuant to the Ohio Revised Code Chapter 6111.


This office has received written notification as the reasons for the above referenced violations, as well as the actions taken or proposed to prevent any further violations.

If you would have any questions regarding the above, please contact me at 937.285.6108.

Sincerely,



Marianne Piekutowski
Environmental Specialist 2
Division of Surface Water



Cc: Jeff Gati, GEAE