



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

March 17, 2008

RE: RETURN TO COMPLIANCE
FAILED ANNUAL STAGE II COMPLIANCE TEST
BP #22354
OHIO EPA ID #0228000202

CERTIFIED MAIL

Denise Lees
BP Products North America
PO Box 6038
Artesia, CA 90702

Dear Ms. Lees:

The annual Stage II compliance test RETESTS conducted at BP #22354 located at 17644 Chillicothe Rd. in Chagrin Falls, Ohio 44022 on February 29, 2008 and March 4, 2008, demonstrated compliance with the requirements of Ohio Administrative Code Rule 3745-21-09 (DDD).

The next Stage II compliance test is due in February 2009.

If you have any questions regarding this letter, please do not hesitate to contact me at (330) 963-1223.

Sincerely,

Dennis Bush
Environmental Manager
Division of Air Pollution Control

DB:bo

cc: Bob Princic, DAPC, NEDO
Tom Kalman, DAPC, CO
Lisa Holscher, USEPA, Region V
Station Manager