



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

June 3, 2008

RE: RETURN TO COMPLIANCE
FAILED 5-YEAR STAGE II COMPLIANCE TEST
WALT WYVILL MARATHON
OHIO EPA ID #0247010636

CERTIFIED MAIL

Walt Wyvill
Walt Wyvill Marathon
109 Cleveland St.
Amherst, OH 44001

Dear Mr. Wyvill:

The 5-year Stage II compliance test RETEST conducted at Walt Wyvill Marathon located at 109 Cleveland St. in Amherst, Ohio 44001 on May 27, 2008, demonstrated compliance with the requirements of Ohio Administrative Code Rule 3745-21-09 (DDD).

The next Stage II compliance test is due in November 2008.

The six months taken to repair the dispensers was certainly excessive. Prompt repair and maintenance of your Stage II vapor control equipment will lead to reduced ozone formation and cleaner air.

I have enclosed a Permit by Rule Notification form. Please complete the form and return it as per the instructions. This will replace any needed Permit-to-Operate or Permit-to-Install and will mean you no longer have to pay the biannual emission fees.

Sincerely,

Dennis Bush
Environmental Manager
Division of Air Pollution Control

DB:bo

cc: Bob Princic, DAPC, NEDO
Tom Kalman, DAPC, CO
Lisa Holscher, USEPA, Region V