



\*4GC0147120100318\*

2010/03/18

4GC01471

HAYDEN'S RESERVE



State of Ohio Environmental Protection Agency

**STREET ADDRESS:**

Lazarus Government Center  
50 W. Town St., Suite 700  
Columbus, Ohio 43215

**Central District Office**

TELE: (614) 728-3778 FAX: (614) 728-3898  
www.epa.state.oh.us

**MAILING ADDRESS:**

P.O. Box 1049  
Columbus, OH 43216-1049

March 18, 2010

Drew Corso  
Newburry Builders  
4885 Aspen Pine Blvd.  
Dublin, OH 43016

**Re: Construction Storm Water Inspection at Hayden Reserve in Hilliard, Ohio**

Dear Mr. Corso:

This letter is written in follow up to a construction storm water inspection I conducted at Hayden Reserve in Hilliard Ohio on March 4, 2010. The inspection was conducted to evaluate the sediment and erosion controls as required by current storm water regulations. The following items were noted:

**Sediment and Erosion Controls:**

- There remains a large stockpile adjacent to the site near the entrance on the south side. This pile must be protected from erosion or demonstrate an approvable alternative.
- All barren areas which remain idle in excess of 21 days must be protected from erosion. All areas of final grade must be protected within 7 days.

**Post Construction Requirements:**

- Please submit to my attention all design criteria to address the post construction requirements of the General Permit. An electronic submittal to [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us), is preferred.

If you have questions regarding this letter or my inspection, please contact me at 614-728-3844 or at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us).

Sincerely,

Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

HK/nsm Hayden Reserve, March 4, 2010

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

