



4GR0050520100312

2010/03/12

4GR00505

OLD DOMINION FREIGHT LINE INC



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Lazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049
Columbus, OH 43216-1049

March 12, 2010

Bill Pressler
Old Dominion Freight Line, Inc.
2885 Alum Creek Drive
Columbus, OH 43207

**Re: Old Dominion Freight Line, Inc. / Franklin County
Industrial Storm Water Permit 4GR00505*DG**

Dear Mr. Pressler:

This letter is written in regard to the storm water inspection that I conducted at Old Dominion Freight Line, Inc., located at 2885 Alum Creek Drive, in Columbus, Ohio. The inspection was conducted on March 8, 2010, to determine compliance with your industrial storm water permit. You stated that your company hauls freight. Overall the facility was very well kept and there was very little oil staining on the parking areas. I did not note any discharges from your facility to a storm water drain or waters of the state and you appear to be in compliance with your permit.

The following items were noted during the inspection:

1. You stated that your company had a storm water pollution prevention plan (SWP3) and a spill prevention plan at the facility. Emergency contact lists were provided in the maintenance shop. A recent SWP3 inspection sheet was provided.
2. There are diesel storage tanks outside in secondary containment. The storm water in the containment area can be directed to an oil-water separator, which is standard protocol.
3. There is another oil-water separator for the maintenance garage.
4. Loading and unloading of freight is done from inside the distribution building,
5. There is a large storm water pond that drains storm water from the entire site. The storm water pond has a manual gate valve to close the pond discharge in case of a spill.

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

6. The diesel fueling station is located inside the maintenance garage. The area is sloped to drain any fuel spills to the oil-water separator.
7. Truck parts, mostly brake drums, and used oil drums were stored in an open roll-offs. These roll-offs should be covered, especially since the roll-offs were not structurally sound and prone to leaking. Please see attached pictures.

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3851.

Sincerely,



Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office

Enclosures

c: Jeff Bohne, DSW/CDO

GS/nsm Old Dominion Freight Line, March 8, 2010

Old Dominion Freight Line
Brake drums stored in open container
Alum Creek Watershed
March 8, 2010
Photo by: Greg Sanders



Old Dominion Freight Line
Roll-offs not structurally sound
Alum Creek Watershed
March 8, 2010
Photo by: Greg Sanders



