



State of Ohio Environmental Protection Agency

STREET ADDRESS:

**Central District Office**

MAILING ADDRESS:

Lazarus Government Center  
50 W. Town St., Suite 700  
Columbus, Ohio 43215

TELE: (614) 728-3778 FAX: (614) 728-3898  
www.epa.state.oh.us

P.O. Box 1049  
Columbus, OH 43216-1049

August 18, 2010

Charles Driscoll  
Nelson Farms Associates Inc.  
495 South High Street # 150  
Columbus, OH 43215

**Re: Construction Storm Water Inspection at Nelson Farms Sections 1, 2, & 3  
Delaware County.  
Permit Number: 4GC01352\*AG**

Dear Mr. Driscoll:

This letter is written regarding the storm water inspection conducted by Vinod Tujalpuram and Abigail Tamkin of Ohio EPA at Nelson Farms 1, 2, and 3 located North of Home Road along SR 315 and East of Liberty Road on July 29, 2010. The Agency understands that these construction activities are currently covered under the General Storm Water Permit Associated with Construction Activities. Based on the site inspection and the General Storm Water Permit, the following items were noted;

**Sediment and Erosion Controls:**

- Silt fence on the north end of the project was impacted by stock piling of dirt, and will require maintenance at this time (Figure 1).
- Several Inlet protections located on site are damaged and must be replaced to minimize sediment runoff into the storm sewer systems (Figure 2). Corrective measures are expected within three days from receipt of this letter.

**Maintenance:**


- The sediment controls implemented on this site will require maintenance or reinstallation to ensure a proper functioning condition. This general permit states that all sediment controls will be inspected and maintained every seven days or within 24 hours of a precipitation event equal to or greater than 0.5 inches. A log of inspection must be maintained on-site for the agency to review.

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

Charles Driscoll  
Nelson Farms Associates Inc.  
Page -2-

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us). A follow-up inspection will be conducted to ensure the conditions of the General Permit are met.

Sincerely,



Harry Kallipolitis  
Storm Water Coordinator  
Ohio EPA, Division of Surface Water  
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm Nelson Farms Section 1,2,&3 7-29-10



Figure 1: Silt fence impacted by Stock piling



Figure 2: Inlet protections are damaged.

