



State of Ohio Environmental Protection Agency

RECEIVED ADDRESS:

Lazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049
Columbus, OH 43216-1049

July 26, 2010

Mollie O'Donnell
City of Columbus
Recreation & Parks Dept.
1111 East Broad Street
Columbus, OH 48205

**Re: Construction Storm Water Inspection at Griggs Reservoir Boathouse
Franklin County.
Permit Number: 4GC02965*AG**

Dear Mr. O'Donnell:

This letter is written regarding the storm water inspection conducted by Vinod Tujalpuram & Elizabeth Schaller of Ohio EPA at the Griggs Reservoir Boathouse located 3033 Thoburn Road, Columbus, Ohio on July 20, 2010. The Agency understands that these construction activities are currently covered under the General Storm Water Permit Associated with Construction Activities. Based on the site inspection and the General Storm Water Permit, the following items were noted:

Sediment and Erosion Controls:

- The silt fence located along the Scioto River end of the project has failed and requires maintenance at this time. Corrective measures are expected within three days from receipt of this letter to avoid potential of escalated action (Figure 1).

Maintenance:

- The sediment controls implemented on this site will require maintenance or reinstallation to ensure a proper functioning condition. This general permit states that all sediment controls will be inspected and maintained every seven days or within 24 hours of a precipitation event equal to or greater than 0.5 inches. A log of inspection must be maintained on site for the agency to review.

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director



Mollie O'Donnell
City of Columbus
Page -2-

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us. A follow-up inspection will be conducted to ensure the conditions of the General Permit are met.

Sincerely,



Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm Griggs Reservoir Boarhouse 7-20-2010



Figure 1: Silt fence requires maintenance.

