



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Cazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049
Columbus, OH 43216-1049

July 23, 2010

William Lemmon
Lemmon & Lemmon Inc
1201 South Main Street
North Canton, OH 44720

**Re: Construction Storm Water Inspection at Parkside Village / Delaware County
Permit Number 4GC02983*AG**

Dear Mr. Lemmon:

This letter is written in follow-up to a construction storm water inspection conducted by Elizabeth Schaller and Abigail Tamkin of Ohio EPA at Parkside Village in Westerville, Ohio on July 16, 2010. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. The following was noted:

Sediment and Erosion Control:

- The retention pond appears to be functioning as intended. The riser must be modified to control sedimentation.
- There is no bank stabilization on the creek on the East side of the property. Controls must be in place to minimize off-site sedimentation (see figure 1).

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm Parkside Village 7-16-2010

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director








Figure 1: Sediment controls needed on creek

