



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Lazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049
Columbus, OH 43216-1049

May 10, 2010

Waste Management Newark Hauling and Transfer Company
100 Ecology Row
Newark, OH 43055

**Re: Preliminary Storm Water Inspection at Waste Management and Newark Hauling:
Permit Number (4GR00450*DG)**

Dear Sir or Madame:

This letter is written in follow-up to a preliminary storm water inspection I conducted at Waste Management Newark Hauling and Transfer Company in Newark, Ohio on April 26, 2010. This facility is currently covered under the General Storm Water Permit Associated with Industrial Activities. This preliminary inspection entailed the evaluation of materials and or processes exposed to storm water. Based on my preliminary inspection, the following items were noted:

Large Fuel Tank:

- Please describe in your response letter the Best Management Practices for the large fueling tank located on this property.

Diked Water Discharge Protocols:

- All discharges associated with the release of storm water accumulated in areas of secondary containment must be inspected and logged prior to the release. The logs must include the authorized representative conducting the release, the time and date, and sampling results to ensure the storm water is not contaminated.

Spill Prevention, Control, and Countermeasure (SPCC) Plan:

- In accordance with 40 CFR, Part 112, this facility may require the development of a SPCC plan if one of the following thresholds are met:
 1. Aggregate above ground oil storage capacity is greater than 1,320 gallons
 2. Buried oil storage capacity is greater than 42,000 gallons
- In the event the SPCC requirements are not triggered for this facility, the SWPPP must include remedial measures in the event of a spill.

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

Inside Floor Drains:

- Please address in your response letter if the inside drains at this facility (if present) drain to a storm or sanitary sewer.

Storm Water Pollution Prevention Plan (SWPPP):

- A SWPPP must be developed specific for this site. The SWPPP must include a site map which clearly delineates all storm water drainage patterns. All storm water outfalls/discharges from the site must be indentified on the SWPPP. All Best Management Practices (BMP's), current and future, must be inclusive in the SWPPP and site map. The SWPPP must be reviewed and updated on a yearly basis to reflect any changes at this facility. Guidance documents for preparing a SWPPP can be found at:

<http://www.epa.gov/npdes/pubs/owm0236a.pdf>

http://www.epa.gov/npdes/pubs/industrial_swppp_guide.pdf

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us. In addition, please provide a written response to this letter within seven days of receipt.

Sincerely,



Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office