



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

February 14, 2011

Don Hurd
Science and Technology Center
2790 Columbus Road
Granville, OH 43023

**Re: Preliminary Storm Water Inspection at Science and Technology
(4GR00112*DG)**

Dear Mr. Hurd:

This letter is written in follow up to a preliminary storm water inspection I conducted at Science and Technology Center located in Granville, Ohio on February 3, 2011. This facility is currently covered under the General Storm Water Permit Associated with Industrial Activities. Based on my preliminary inspection and 40 CFR 122.26, the following are noted:

Storm Water Pollution Prevention Plan (SWPPP)

- A SWPPP must be developed specific for this site. The SWPPP must include a site map which clearly delineates all storm water drainage patterns. All storm water outfalls/discharges from the site must be identified on the SWPPP. All Best Management Practices (BMP's), current and future must be inclusive in the SWPPP and site map. The SWPPP must be reviewed and updated on a yearly basis to reflect any changes at this facility. Guidance documents for preparing a SWPPP can be found at:

<http://www.epa.gov/npdes/pubs/owm0236a.pdf>

http://www.epa.gov/npdes/pubs/industrial_swppp_guide.pdf

No Exposure Certification:

Ohio EPA has adopted the federal "No Exposure Certification" application form and is using the federal guidance document to determine whether facilities are eligible for the no exposure exemption. The "No Exposure Certification" exempts the facility from Storm Water Permitting requirements provided all processes and materials are stored under roof and you qualify in accordance with filing instructions (links) below. Facilities may apply for this exclusion. "No Exposure Certification" guidance, application form and instructions document is available at:

Central District Office
50 West Town Street, Suite 700
P.O. Box 1049
Columbus, OH 43216-1049

614 | 728 3778
614 | 728 3898 (fax)
www.epa.ohio.gov

Don Hurd
Science and Technology Center
Page -2-

http://cfpub.epa.gov/npdes/stormwater/exposure.cfm?program_id=6. Applicants should complete the form according to the instructions in the guidance and mail it to:

Ohio Environmental Protection Agency
Division of Surface Water
Attn: Michael Joseph
P.O. Box 1049
Columbus, OH 43216-1049

If you qualify for no exposure certification, you are exempt from permit requirements until your facility no longer qualifies for no exposure certification. If your facility changes and can no longer claim no exposure to storm water you must submit the appropriate permit application for storm water discharge.

The "No Exposure Certification" must be filled out and submitted every five years.

Additional information regarding "No Exposure Certification"
http://www.epa.state.oh.us/dsw/storm/ind_noexp_cert.aspx

The actual form you need to fill out is located at:
http://www.epa.gov/npdes/pubs/noexpoform_app4.pdf)

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us. ***At this time, I am formally requesting an on-site inspection to determine the appropriate permitting requirements for this operation.***

Sincerely



Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO