



4GC0354820110815

2011/08/15

4GC03548

WECONNECT COMMUNITY DATA CENTER



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

August 15, 2011

Glenn Mohre
Corna Kokosing Construction Company
6235 Westerville Road
Westerville, OH 43081

**Re: Construction Storm Water Inspection at WeConnect Community Data Center
Franklin County
Permit Number: 4GC03548 *AG**

Dear Mr. Mohre:

This letter is written regarding a storm water inspection conducted by Greg Mann and Daelann Farnlacher of the Ohio EPA at WeConnect Community Data Center located at 35 College View Road Westerville, Ohio on August 5, 2011. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- During the inspection, a storm drain was noted on the north side of the facility lacking inlet protection (see Figure 1). Please cover the inlet to minimize off-site sediment transport.
- It was noted that the new storm catch basins are allowing storm water to by-pass the inlet protection, allowing sediment laden storm water to discharge off site. Please eliminate the by-pass.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW / CDO

HK/nsm WeConnect Community Data Center 8-5-2011

Central District Office
50 West Town Street, Suite 700
P.O. Box 1049
Columbus, OH 43216-1049

614 | 728 3778
614 | 728 3898 (fax)
www.epa.ohio.gov

