



## REGIONAL AIR POLLUTION CONTROL AGENCY

Serving Clark, Darke, Greene, Miami, Montgomery & Preble Counties

117 South Main Street, Dayton, Ohio 45422-3280

937-225-4435 — Fax: 937-225-3486

www.rapca.org

April 26, 2011

### Certified Mail

Murad Jallaq and/or  
Mohammed Widdi  
Marathon  
2001 East Main Street  
Springfield, OH 45503

RE: **Ohio EPA Facility ID 0812100430**  
**Failure to pass annual stage II vapor recovery compliance testing**

### WARNING LETTER

Dear Mr. Jallaq/Mr. Widdi:

On February 23, 2011, the Regional Air Pollution Control Agency (RAPCA) conducted an inspection and witnessed a performance test of the Marathon gasoline dispensing facility (GDF) located at 2001 East Main Street in Springfield, Ohio. The purpose of this inspection and performance test was to determine the GDF's compliance status with applicable state and local air pollution control regulations. This inspection/test at Marathon revealed violations of these regulations.

Pursuant to Ohio Administrative Code (OAC) rule and Clark County Combined Health District Air Pollution Control Regulations (CCCHDAPCR) section 3745-21-09 (DDD)(2) and in accordance with the testing requirements specified in CARB Executive Order G-70-154-AA for Tokheim MaxVac stage II vapor recovery systems, static leak testing and air to liquid ratio (A/L) testing shall be successfully conducted at least once in each consecutive twelve-month period. Marathon failed to show compliance with OAC rule and CCCHDAPCR section 3745-21-09 (DDD)(2) and CARB Executive Order G-70-154-AA on February 23, 2011 through the completion of a successful static leak test and A/L test. On this date, static leak testing failed on the Tokheim MaxVac stage II vapor control system and no A/L testing was attempted. RAPCA spoke to Mohammed Widdi on April 5, 2011, regarding the need to reschedule the required static leak and A/L testing. RAPCA was told that a testing firm would be contacted to get the tests rescheduled at Marathon but, to this date, no testing has been rescheduled with RAPCA at this GDF.

Marathon (Ohio EPA Facility ID 0812100430)

April 26, 2011

Page 2


Failing to demonstrate compliance with the stage II vapor recovery compliance testing requirements is a violation of OAC rule and CCCHDAPCR section 3745-21-09 (DDD)(2), CARB Executive Order G-70-154-AA, and Ohio Revised Code (ORC) 3704.05.

Since the above noted GDF is currently operating in violation of OAC rule and CCCHDAPCR section 3745-21-09 (DDD)(2), CARB Executive Order G-70-154-AA and ORC 3704.05, it is imperative that Marathon ensure that repairs are made to this site to correct any deficiencies and reschedule testing to demonstrate compliance.

**Marathon shall respond within fourteen (14) days after receipt of this letter.** The response shall include the intended retest date for this GDF. Your tester should contact Lynn Thompson at (937) 225-4437, to ensure a RAPCA representative is present at your scheduled testing.

Failure to perform the required testing will subject this facility to further enforcement actions, which may include penalties. If you have any questions or comments concerning this matter, please feel free to contact me at (937) 225-5923.

Sincerely,



Brandie K. Lehman  
Air Pollution Control Specialist

cc:	Jeff Canan	RAPCA
	Tom Kalman	OEPA
	William MacDowell	USEPA, Region V

<b>COMPLETE THIS SECTION</b> Items 1, 2, and 3. Also complete Restricted Delivery if Restricted Delivery is desired. Your name and address on the reverse that we can return the card to you. Attach this card to the back of the mailpiece, or on the front if space permits.		<b>COMPLETE THIS SECTION ON DELIVERY</b>	
1. Article Addressed to:  Murah Jallaq and/or Mohammed Widdi Marathon 2001 East Main St. Springfield, Ohio 45503		A. Signature <input checked="" type="checkbox"/> <i>M. Widdi</i>	<input type="checkbox"/> Agent <input type="checkbox"/> Addressee
		B. Received by (Printed Name) MARIO WIDDI	C. Date of Delivery 4-28-11
		D. Is delivery address different from item 1? <input type="checkbox"/> Yes If YES, enter delivery address below: <input type="checkbox"/> No	
		Service Type <input type="checkbox"/> Certified Mail <input type="checkbox"/> Express Mail <input type="checkbox"/> Registered <input type="checkbox"/> Return Receipt for Merchandise <input type="checkbox"/> Insured Mail <input type="checkbox"/> C.O.D.	
2. Article Number (Transfer from service label)		7010 3090 0000 7674 5799	
PS Form 3811, February 2004		Domestic Return Receipt	

**CONTROL AGENCY**  
 Perry & Preble Counties  
 45422-3280  
 25-3486

2001 East Main Street  
 Springfield, OH 45503

**RE: Ohio EPA Facility ID 0812100430  
 Failure to pass annual stage II vapor recovery compliance testing**

**WARNING LETTER**

Dear Mr. Jallaq/Mr. Widdi:

On February 23, 2011, the Regional Air Pollution Control Agency (RAPCA) conducted an inspection and witnessed a performance test of the Marathon gasoline dispensing facility (GDF) located at 2001 East Main Street in Springfield, Ohio. The purpose of this inspection and performance test was to determine the GDF's compliance status with applicable state and local air pollution control regulations. This inspection/test at Marathon revealed violations of these regulations.

Pursuant to Ohio Administrative Code (OAC) rule and Clark County Combined Health District Air Pollution Control Regulations (CCCHDAPCR) section 3745-21-09 (DDD)(2) and in accordance with the testing requirements specified in CARB Executive Order G-70-154-AA for Tokheim MaxVac stage II vapor recovery systems, static leak testing and air to liquid ratio (A/L) testing shall be successfully conducted at least once in each consecutive twelve-month period. Marathon failed to show compliance with OAC rule and CCCHDAPCR section 3745-21-09 (DDD)(2) and CARB Executive Order G-70-154-AA on February 23, 2011 through the completion of a successful static leak test and A/L test. On this date, static leak testing failed on the Tokheim MaxVac stage II vapor control system and no A/L testing was attempted. RAPCA spoke to Mohammed Widdi on April 5, 2011, regarding the need to reschedule the required static leak and A/L testing. RAPCA was told that a testing firm would be contacted to get the tests rescheduled at Marathon but, to this date, no testing has been rescheduled with RAPCA at this GDF.

