



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Central District Office

MAILING ADDRESS:

Lazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

P.O. Box 1049
Columbus, OH 43216-1049

September 15, 2010

Michael Cashey
Fibertech of Ohio Inc.
Fibertech Plant #2
2000 Kenskill Avenue
Washington Court House, OH 43160

**Re: Fibertech Plant #2, Fayette County
Industrial Storm Water Permit 4GR00121*DG**

Dear Mr. Cashey:

This letter is written in regard to the storm water inspection that I conducted at Fibertech Plant #2, located at 2000 Kenskill Avenue, in Washington Court House, Ohio. The inspection was conducted on August 31, 2010, to determine compliance with your industrial storm water permit. Your company makes laminated plywood panels for truck bodies. I inspected the outside of your facility for compliance with regard to your industrial storm water permit. There were no raw materials or final product stored outside. You stated that loading and unloading of raw materials and final product were done inside at this plant. I did not note any discharges from your facility to a storm water drain or waters of the state and you appear to be in compliance with your permit. Since you do not have any exposure to storm water, you may request a No Exposure Certification. This certification would exempt you from an industrial storm water permit. Please see the following on this certification:

No Exposure Certification:

Ohio EPA has adopted the federal "No Exposure Certification" application form and is using the federal guidance document to determine whether facilities are eligible for the no exposure exemption. The "No Exposure Certification" exempts the facility from Storm Water Permitting requirements provided all processes and materials are stored under roof and you qualify in accordance with filing instructions (links) below. Facilities may apply for this exclusion. "No Exposure Certification" guidance, application form and instructions document is available at: http://cfpub.epa.gov/npdes/stormwater/exposure.cfm?program_id=6. Applicants should complete the form according to the instructions in the guidance and mail it to:

Ohio Environmental Protection Agency
Division of Surface Water
Attn: Michael Joseph
P.O. Box 1049
Columbus, OH 43216-1049

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korteski, Director

Michael Cashey
Fibertech of Ohio Inc.
Page -2-

If you qualify for no exposure certification, you are exempt from permit requirements until your facility no longer qualifies for the No Exposure Certification. If your facility changes and can no longer claim no exposure to storm water you must submit the appropriate permit application for storm water discharge. The "No Exposure Certification" must be filled out and submitted every five years.

Additional information regarding "No Exposure Certification"
http://www.epa.state.oh.us/dsw/storm/ind_noexp_cert.aspx

The actual form you need to fill out is located at:
http://www.epa.gov/npdes/pubs/msgp2008_appendixk.pdf.

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3851.

Sincerely,



Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office

c: Jeff Bohne, DSW/CDO

GS/nsm Fibertech, Plant #2, August 31, 2010