

marathu



REGIONAL AIR POLLUTION CONTROL AGENCY

Serving Clark, Darke, Greene, Miami, Montgomery & Preble Counties
117 South Main Street, Dayton, Ohio 45422-1280
937-225-4435 — Fax: 937-225-3486
www.rapca.org

June 11, 2007

Certified Mail

Randy Singh
Sunoco-R&A Corporation
7851 Old Troy Pike
Huber Heights, OH 45424

**RE: Ohio EPA Premises No. 0857771843
Sunoco-R&A Corporation - 4600 Old Troy Pike, Huber Heights, OH 45424
Failure to pass annual stage II vapor recovery compliance testing**

WARNING LETTER

Dear Mr. Singh:

On January 11, 2007, the Regional Air Pollution Control Agency (RAPCA) conducted an inspection and witnessed a performance test of the Sunoco-R&A Corporation gasoline dispensing facility (GDF), located at 4600 Old Troy Pike in Huber Heights, Ohio. The purpose of this inspection and performance test was to determine the GDF's compliance status with applicable state and local air pollution control regulations. This inspection/test at Sunoco-R&A Corporation revealed violations of state and local air pollution control regulations.

Pursuant to Ohio Administrative Code (OAC) rule and Montgomery County Combined General Health District Air Pollution Control Regulations (MCCGHDAPCR) section 3745-21-09 (DDD)(2), and in accordance with the testing requirement specified in CARB Executive Order G-70-153-AD, Static Leak testing contained in OAC rule 3745-21-10, Appendix A, and Air to Liquid Ratio (A/L) testing shall be successfully conducted at least once in each consecutive twelve-month period. Sunoco-R&A Corporation failed to show compliance with OAC rule and MCCGHDAPCR section 3745-21-09 (DDD)(2), through the completion of a successful Static Leak test and A/L test on January 11, 2007. Failing to demonstrate compliance with the testing requirements is a violation of OAC rule and MCCGHDAPCR section 3745-21-09 (DDD)(2), OAC rule and MCCGHDAPCR section 3745-15-04, and Ohio Revised Code (ORC) section 3704.05. On January 11, 2007, a Board of Health Order was issued to Sunoco-R&A Corporation to retest within a thirty (30) day time period, as too much ullage caused test cancellation on this date. As of this date, retesting has not been conducted.

Since the above noted GDF is currently operating in violation of OAC rules and MCCGHDAPCR sections 3745-21-09 (DDD)(2) and 3745-15-04, and CARB Executive Order


Sunoco-R&A Corporation
June 11, 2007
Page 2

G-70-153-AD, it is imperative that Sunoco-R&A Corporation promptly reschedule testing to demonstrate compliance.

Sunoco-R&A Corporation shall respond within fourteen (14) days after receipt of this letter. The response shall include the intended retest date for this GDF. Your tester should contact Casie Lord, at (937) 225-5939, to ensure a RAPCA representative is present at your scheduled testing.


Failure to perform the required testing will subject this facility to further enforcement actions, which may include penalties. If you have any questions or comments concerning this matter, please feel free to contact me at (937) 225-5923.

Sincerely,



Brandie K. Lehman
Air Pollution Control Specialist
Abatement Unit

cc:	Jeff Canan	RAPCA
	Tom Kalman	OEPA
	Lisa Holscher	USEPA



REGION
Serving Cl

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

RANDY SINGH
SUNOCO-R&A CORP.
7851 OLD TROY PIKE
HUBER HEIGHTS, OH 45424

4245 Gibson

2. Article Number
(Transfer from service label)

7004 1160 0000 6165 8953

PS Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1

COMPLETE THIS SECTION ON DELIVERY

A. Signature

X *Jeresa Jones* Agent Addressee

B. Received by (Printed Name)

C. Date of Delivery

6-13-07

D. Is delivery address different from item 1? Yes
If YES, enter delivery address below: No

3. Service Type

- Certified Mail Express Mail
- Registered Return Receipt for Merchand
- Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee) Yes

Certified Mail

Randy Singh
Sunoco-R&A Corporation
7851 Old Troy Pike
Huber Heights, OH 45424

**RE: Ohio EPA Premises No. 0857771843
Sunoco-R&A Corporation - 4600 Old Troy Pike, Huber Heights, OH 45424
Failure to pass annual stage II vapor recovery compliance testing**

WARNING LETTER

Dear Mr. Singh:

On January 11, 2007, the Regional Air Pollution Control Agency (RAPCA) conducted an inspection and witnessed a performance test of the Sunoco-R&A Corporation gasoline dispensing facility (GDF), located at 4600 Old Troy Pike in Huber Heights, Ohio. The purpose of this inspection and performance test was to determine the GDF's compliance status with applicable state and local air pollution control regulations. This inspection/test at Sunoco-R&A Corporation revealed violations of state and local air pollution control regulations.

Pursuant to Ohio Administrative Code (OAC) rule and Montgomery County Combined General Health District Air Pollution Control Regulations (MCCGHDAPCR) section 3745-21-09 (DDD)(2), and in accordance with the testing requirement specified in CARB Executive Order G-70-153-AD, Static Leak testing contained in OAC rule 3745-21-10, Appendix A, and Air to Liquid Ratio (A/L) testing shall be successfully conducted at least once in each consecutive twelve-month period. Sunoco-R&A Corporation failed to show compliance with OAC rule and MCCGHDAPCR section 3745-21-09 (DDD)(2), through the completion of a successful Static Leak test and A/L test on January 11, 2007. Failing to demonstrate compliance with the testing requirements is a violation of OAC rule and MCCGHDAPCR section 3745-21-09 (DDD)(2), OAC rule and MCCGHDAPCR section 3745-15-04, and Ohio Revised Code (ORC) section 3704.05. On January 11, 2007, a Board of Health Order was issued to Sunoco-R&A Corporation to retest within a thirty (30) day time period, as too much ullage caused test cancellation on this date. As of this date, retesting has not been conducted.

Since the above noted GDF is currently operating in violation of OAC rules and MCCGHDAPCR sections 3745-21-09 (DDD)(2) and 3745-15-04, and CARB Executive Order