



State of Ohio |

OH5054212 JACKSON/MILTON SERVICE AREA PWS

57 05/12/10 A

Nor



TELE: (330

2110 East Aurora Rd.
Twinsburg, Ohio 44087

ernor
ernor

Chris Korleski, Director

May 4, 2010

RE: MAHONING COUNTY
JACKSON MILTON SERVICE AREA
COMMUNITY WATER SYSTEM
PWS ID # OH5054212
LEAD AND COPPER

Mr. Joseph DeNiro, Sanitary Engineer
Mahoning County Sanitary Engineering Dept.
761 Industrial Road
Youngstown, OH 44509

RE: Failure to Submit Corrosion Control Study

Dear Mr. DeNiro:

This letter is notification that the Jackson Milton Service Area community water system is in violation of the Ohio Administrative Code (OAC) for failure to submit a Corrosion Control Study as specified in OAC rules 3745-81-80 through 3745-81-89.

Submit the required Corrosion Control Study for optimal corrosion control treatment no later than June 30, 2010.

Thank you for your cooperation and if you have any questions, feel free to contact me at (330) 963-1199.

Sincerely,

Stephen Bopple, P.E.
Environmental Engineer
Division of Drinking and Ground Waters

SB:ds

cc: Kim Etters, DDAGW, NEDO