



**Environmental
Protection Agency**

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

May 3, 2012

**HARRISON COUNTY
HARRISON COUNTY GARAGE
DHWM-SEDO
OHD987021177**

Mr. Robert Sterling
County Engineer
Harrison County Courthouse
100 West Market Street
Cadiz, Ohio 43907

Dear Mr. Sterling:

On April 17, 2012, Ohio EPA conducted a post-closure compliance evaluation inspection of the Harrison County Garage Drum Disposal Area located in Cadiz, Ohio. The reason for this inspection was to determine compliance with the approved post-closure plan, Ohio's hazardous waste laws and regulations found in Ohio Revised Code (ORC) Chapter 3734. and Ohio Administrative Code (OAC) Chapter 3745.

Based on the inspection, the following violation of Ohio's hazardous waste regulations and requirement of the approved post-closure plan was observed. In order to correct this violation, you must complete the following and forward to my attention the required information within 30 days of receipt of this letter:

Post-closure care and use of property, OAC Rule 3745-55-17(A)(1)(b): Post-closure care for each hazardous waste management unit subject to the requirements of OAC Rules 3745-55-17 through 3745-55-20 must begin after completion of the closure unit and continue for thirty years after the date of completing closure and must consist of at least the following: Maintenance and monitoring of waste containment systems in accordance with the requirements of OAC Rules 3745-54-90 through 3745-54-101, 3745-56-20 through 3745-56-31, 3745-56-50 through 3745-56-59, 3745-56-70 through 3745-56-83, 3745-57-02 through 3745-57-17 and 3745-57-90 through 3745-57-93.

During the April 17, 2012 inspection, vegetation was observed growing through the cap near the large pipe riser which protrudes through the asphalt cap. The vegetation growing in this area will compromise the integrity of the asphalt cap and must be removed. According to the post-closure inspection checklist in the approved post-closure plan, vegetation growing through the cap will be removed and the composite asphalt cap will be repaired. To demonstrate compliance with this post-closure care plan and applicable regulations, the vegetation must be removed, the cap repaired and photographic documentation must be sent to this office for review.

HARRISON COUNTY GARAGE
MAY 3, 2012
PAGE 2

If you should have any questions, please contact me at (740) 380-5443.

Sincerely,

A handwritten signature in black ink, appearing to read "Trevor L. Irwin". The signature is fluid and cursive, with a large initial "T" and "I".

Trevor L. Irwin, RS
Environmental Specialist II
Division of Environmental Response and Revitalization
Southeast District Office

TLI/cb

Notice:
Ohio EPA's failure to list specific deficiencies or violations in this letter does not relieve your company from having to comply with all applicable regulations.