



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

September 24, 2008

RE: GERDAU MACSTEEL
(ATMOSPHERE ANNEALING)
STARK COUNTY
OHD 122 004 906
LQG, RETURN TO COMPLIANCE

Mr. John Warner
Environmental Manager Rep.
Gerdau Macsteel Atmosphere Annealing
1501 Raff Rd. SW
Canton, OH 44710

Dear Mr. Warner:

On August 29, 2008, the Ohio EPA received a response to our Notice of Violation Letter dated July 30, 2008. Your response included: waste evaluation information for refractory brick, contingency plan and spill control information, testing and maintenance of equipment, and inspection checklist documentation.

Based on review of this submittal and an email confirmation of emergency equipment received on September 11, 2008, it appears that Gerdau Macsteel Atmosphere Annealing has adequately abated all violations identified during the June 6, 2008 CEI at the Raff Road, Canton facility.

If you have any questions, you may contact me at (330) 963-1146 or at:
ron.shadrach@epa.state.oh.us.

Sincerely,

Ronald J. Shadrach
District Representative
Division of Hazardous Waste Management

RJS:ddw

ec: Frank Popotnik, DHWM, NEDO

NOTICE: Ohio EPA's failure to list specific deficiencies or violations in this letter does not relieve your company from having to comply with all applicable regulations.