



State of Ohio Environmental Protection Agency
Southwest District

401 East Fifth Street
Dayton, Ohio 45402-2911

TELE: (937)285-6357 FAX: (937)285-6249
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lt. Governor
Chris Korleski, Director

July 30, 2007

Mr. Allen Brotherton
Highland Precision Plating
6940 Willettsville Pike
P.O. Box 784
Hillsboro, Ohio 45133

**Re: Highland Precision Plating – Indirect Discharge Permit
OHP000074;1DP00008*CP – NOTICE OF VIOLATION - SNC Determination**

CERTIFIED MAIL

Dear Mr. Brotherton:

This office has received the self-monitoring report for the above referenced facility. Our review indicates violations of the conditions of your indirect discharge permit. The specific instances of non-compliance and/or deficiencies were as follows:

EFFLUENT LIMIT VIOLATIONS

Station No. 1DP00008001

<i>Parameter</i>	<i>Code</i>	<i>Date</i>	<i>Reported</i>	<i>Units</i>	<i>Permit Limit</i>
Nickel, Total	01067	03/07	3,280	ug/L	2,380 ug/L
Nickel, Total	01067	06/07	5,194	ug/L	2,380 ug/L
Zinc, Total	01092	06/07	9,325	ug/L	1,480 ug/L

Please be advised that failure to comply with the effluent limitations, or to satisfy monitoring or reporting requirements of your NPDES permit may be cause for enforcement action pursuant to the Ohio Revised Code Chapter 6111. Please note that the facility has been determined to be in Significant Non-Compliance for the first half of 2007 for violations of the Technical Review Criteria (TRC) for average nickel violations.




July 30, 2007
Page 2

Additional sampling and reasons for the violations were provided to Ohio regarding these violations. The last sampling event showed the facility returned to compliance.

If you would have any questions regarding the above, please contact me at 937.285.6108.

Sincerely,

A handwritten signature in black ink, appearing to read 'Marianne Piekutowski', followed by a long horizontal flourish.

Marianne Piekutowski
District Pretreatment Coordinator
Division of Surface Water

Cc: Julia Zhang, DSW/CO
Brandon Leeth, Hillsboro

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:


 ALLEN BROTHERTON
 HIGHLAND PRECISION PLATING
 6940 WILLETSVILLE PIKE
 P O BOX 784
 HILLSBORO OH 45133

2. Article Number

(Transfer from service label)

7007 0220 0001 2491 5277

PS Form 3811, February 2004

COMPLETE THIS SECTION ON DELIVERY

A. Signature

Allen Brotherton
 Agent
 Addressee

B. Received by (Printed Name)

Allen Brotherton

C. Date of Delivery

8/3/07

D. Is delivery address different from item 1? Yes

If YES, enter delivery address below: No

3. Service Type

- Certified Mail Express Mail
- Registered Return Receipt for Merchandise
- Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee)

Y N

Domestic Return Receipt

102595-02-M-154

U.S. Postal Service™

CERTIFIED MAIL™ RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com

OFFICIAL USE

Postage	\$	
Certified Fee		
Return Receipt Fee (Endorsement Required)		
Restricted Delivery Fee (Endorsement Required)		
Total Postage &		

Postmark Here

<i>Sent To</i>	ALLEN BROTHERTON
<i>Street, Apt. No., or PO Box No.</i>	HIGHLAND PRECISION PLATING 6940 WILLETSVILLE PIKE
<i>City, State, ZIP+4</i>	P O BOX 784 HILLSBORO OH 45133

7007 0220 0001 2491 5277

PS Form 3800, August 2006 See Reverse for Instructions