



State of Ohio Environmental Protection Agency

Northwest District Office

347 North Dunbridge Road
Bowling Green, OH 43402-9398

TELE: (419) 352-8461 FAX: (419) 352-8468
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

Re: Henry County
0335010105
Campbell Soup Company
Stack Test Results
Notice of Violation/HPF

July 17, 2007

CERTIFIED MAIL

Mr. Robert Counselman
Campbell Soup Company
12-773 State Route 110
Napoleon, Ohio 43545

Dear Mr. Counselman:

The stack tests conducted on April 10-12, and April 20th, 2007, on Ohio EPA emissions units B001-B004 and P005, have been reviewed. The testing was conducted in conformance with Ohio EPA methods and procedures. Our review confirms the following reported data is accurate:

**Critical Test Data - PM
(In Three Run Averages)**

Emissions Unit	Actual Emission Rate	Allowable Emission Rate	Source Operating Rate	Maximum Source Operating Rate
B001 & B002	0.14 lb/MMBtu	0.13 lb/MMBtu	71.5 MMBtu/hr (B001) 71.5 MMBtu/hr (B002)	98.4 MMBtu/hr
B003	0.04 lb/MMBtu	0.13 lb/MMBtu	78 MMBtu/hr	114 MMBtu/hr
B004	0.049 lb/MMBtu	0.13 lb/MMBtu	52.1 MMBtu/hr	114 MMBtu/hr
P005	1.18 lbs/hr	4.1 lbs/hr	1900 lbs/hr	2000 lbs/hr

Emissions units B001 and B002 were being operated in violation of their allowable emissions rates (violations of the Title V permit term and condition A.I.1, OAC rule 3745-17-10(c) and Ohio Revised Code 3704.05). Also, emissions units B001 and B002 were only being operated at 72.7% of their maximum heat input rates.

Mr. Robert Counselman
July 17, 2007
Page 2

B003 and B004 were only being operated at 68.4 and 45.7% of their maximum heat input rates, respectively. The Ohio EPA can not accept compliance testing at less than the maximum heat input rates.

This office is requesting that the facility submit a written response to this letter which includes, at a minimum, a compliance plan and schedule. The facility is required to submit this information by no later than August 15, 2007. Please note that the submission of the requested information to respond to this letter does not constitute a waiver of the Ohio EPA's authority to seek civil penalties pursuant to ORC section 3704.06.

The Ohio EPA acknowledges receipt of a misplaced report for a stack test performed on the vegetable waste dryer (P005) on August 7, 2002. That test could not be evaluated because no source operating data was collected and the test was not witnessed. However, Campbell has retested and demonstrated this unit to be in compliance with the 2007 test.

You may contact me at (419) 373 -3139, should you have any questions or comments regarding this letter.

Sincerely,



Robert G. Teer
Division of Air Pollution Control

//lr

pc: Don Waltermeyer, DAPC-NWDO
Lisa Holscher, US EPA Region 5
Robert Teer, DAPC-NWDO
Tom Kalman, DAPC/CO
Tom Sattler, DAPC-NWDO
Wendy Licht, DAPC-NWDO
~~DAPC-NWDO File~~ →
Stack File

U.S. Postal Service™
CERTIFIED MAIL™ RECEIPT
 (Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com

7006 3450 0001 0661 4649

Postage	\$ 41
Registration Fee	2.65
Postage and Fee Total	2.15
Total	\$ 52.1



7006 3450 0001 0661 4649
 RECEIVED BY
 ROBERT AUSTERMILLER - CAMPBELL SOAP CO
 12-773 STATE ROUTE 110
 PAROLEON ON 43545

PS Form 3800, August 2006

See Reverse for Instructions

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, with the front of the card facing forward.

1. Addressee:

MR ROBERT AUSTERMILLER
 CAMPBELL SOAP COMPANY
 12-773 STATE ROUTE 110
 PAROLEON ON 43545

COMPLETE THIS SECTION ON DELIVERY

A. Signature

Robert Austermiller Initial Print Name

B. Received by (Printed Name)

ROBERT AUSTERMILLER

C. Date of Delivery

D. Is delivery address different from item 1? Yes

If YES, enter delivery address below: No

3. Service Type

- Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee)

Yes

7006 3450 0001 0661 4649