



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

February 13, 2009

RE: PERMIT #3PB00031

Mr. Edward Trego
Village of Mantua
4736 East High Street
Mantua, Ohio 44255

Dear Mr. Trego:

This letter will document a pre-permit compliance inspection conducted at the Mantua WWTP on February 11, 2009.

A review of facility monitoring data for the time period January through December 2008 has detected the following violations.

Reporting Period	Station	Parameter	Limit Type	Limit	Reported Value	Violation Date
March 2008	001	Mercury, Total	30D Conc	0.0013	.2	3/1/2008
March 2008	001	Mercury, Total	30D Qty	0.00000246	.00032	3/1/2008
March 2008	001	Total Suspended Solids	7D Qty	34.1	34.7779	3/15/2008
June 2008	001	Mercury, Total	30D Conc	0.0013	1.24	6/1/2008
June 2008	001	Mercury, Total	30D Qty	0.00000246	.00107	6/1/2008
August 2008	001	Mercury, Total	30D Conc	0.0013	2.25	8/1/2008
August 2008	001	Mercury, Total	30D Qty	0.00000246	.00159	8/1/2008
December 2008	001	Mercury, Total	30D Conc	0.0013	5.31	12/1/2008
December 2008	001	Mercury, Total	30D Qty	0.00000246	.00419	12/1/2008
December 2008	001	Mercury, Total	1D Conc	3.4	5.31	12/23/2008

At the time of my inspection the clarifier sludge blanket had lifted and was discharging over the weirs in both tanks. These solids were then observed in the effluent channel. Influent flow was elevated due to snow melt and rain. Previous inspections of the plant have not identified this problem before. Please respond to this office with measures taken to correct this as well as identify possible reasons for this event.

Should you have further questions, please call me at (330) 963-1134.

Sincerely,

William J. Zawiski
Environmental Scientist
Division of Surface Water

WJZ/mt