



State of Ohio Environmental Protection Agency

Southwest District Office

401 E. Fifth St.
Dayton, Ohio 45402

TELE: (937) 285-6357 FAX: (937) 285-6249
www.epa.ohio.gov

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korteski, Director

December 29, 2009

Re: **Brookside Village MHP**
Clark County
Community Water System
PWS ID: 1200112

Brookside Village MHP
JGR Properties
Attn: James Geyer, Owner
P.O. Box 610
Oxford, OH 45056

Subject: Monthly Operating Report, Failure to Submit

Dear Mr. Geyer:

According to OAC-3745-83-01 Operational Requirements, each community public water system shall prepare an operation report for each month of operation. This report should contain the free and total chlorine daily residuals in the distribution and at the plant tap. For the month of November 2009, Brookside Village MHP public water system failed to monitor for the free and total chlorine residuals daily at the plant tap and in the distribution. The report contains several days of missing data. This is a violation of the rule. Brookside Village MHP public water system shall provide an explanation in writing to Ohio EPA concerning this matter and explain what steps will be taken to ensure that the free and total chlorine residuals are taken in the distribution system and at the plant tap.

If you have any further questions or comments concerning your water system, please feel free to contact me at 937-285-6085.

Sincerely,

Tya Darden

Division of Drinking and Groundwaters
Public Drinking Water Unit

cc: Dave Evans, Ohio EPA, DDAGW, CO
Charles Crosbie, 6385 Harvest Street, Springfield, OH 45502
File

TD/mab