



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Lazarus Government Center  
50 W Town Street, Suite 700  
Columbus, OH 43215

TELE: (614) 644-2752  
www.epa

OH8751612

2nd Shot Golf

12/4/2009



December 4, 2009

2ND SHOT GOLF LLC  
8205 FREMONT PIKE  
PERRYSBURG, OH 43551

Re: WOOD COUNTY  
2ND SHOT GOLF PWS  
Transient Noncommunity Water System  
PWS ID: OH8751612  
STU ID: 8760962

**DELINQUENCY NOTICE - ACTION REQUIRED**

**Subject: Failure to Monitor Drinking Water**

2ND SHOT GOLF PWS is in violation of Ohio Administrative Code Rule 3745-81-23 for failing to monitor your drinking water during the June 1, 2009 to October 31, 2009 monitoring period and/or report results for the following contaminants: NITRATE (AS N).

2ND SHOT GOLF PWS must promptly take the following actions.

- A. **If sample was taken during this monitoring period,**
  - a. Call your laboratory and have them submit the results to Ohio EPA.
  - b. Contact this office at (614) 644-2752 to consult with us on this issue.

- OR -
- B. **If sample was not taken during or after this monitoring period,**
  - a. Immediately take a sample of your drinking water from the first tap following treatment.
  - b. Submit the sample for analysis to a certified laboratory on the enclosed list.

- OR -
- C. **If sample was taken after this monitoring period,** contact this office at (614) 644-2752.

Your prompt attention to this matter is appreciated. Continued failure to sample during your scheduled time period may lead to enforcement which may include penalties. If you have questions, please call me at (614) 644-2752.

Sincerely,

Justin Burke  
Division of Drinking and Ground Waters

Enclosure: Laboratory List

cc: Superintendent/Manager; DDAGW-NWDO file; DDAGW-CO file

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director