



**Environmental
Protection Agency**

Tom Carper, Governor
Les Fisher, Lt. Governor
Chris Kuntz, Director

July 14, 2010

RE: FEDEX GROUND
3GR00885*DG
STORMWATER
SUMMIT COUNTY

Mr. Paul Sojda
Senior Manager
FedEx Ground Package System Inc
3201 Columbia Rd.
Richfield, Ohio 44286

Dear Mr. Sojda:

On July 12, 2010 this writer conducted an inspection of your facility, located at 3201 Columbia Road in Richfield, Ohio to determine compliance with your Industrial General Storm Water NPDES permit referenced above. The following observations were made:

General:

1. The site is a ground package delivery company for northeast Ohio.
2. Drainage on the site empties from a series of catch basins into a ditch along the border of the property.
3. Drainage from the fuel island passes through an oil-water separator then is pumped to sanitary lines.
4. Truck washes are conducted both inside and outside. The water from the outside washes is collected before it enters storm water drains.

Inspection Observations:

- Overall, the site was visually clean and well maintained.

If you should have any questions concerning this letter, feel free to contact this writer at (330) 963-1125 or by email lindsey.olmstead@epa.state.oh.us.

Sincerely,

Lindsey A. Olmstead
Assistant to the District Engineer
Division of Surface Water

LAO/mt

Northeast District Office
2110 East Aurora Road
Twinsburg, OH 44087-1924

330 | 963 1200
330 | 487 0769 (fax)
www.epa.ohio.gov