



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

October 23, 2008

RE: HOLMES COUNTY AIRPORT AUTHORITY
GENERAL STORMWATER PERMIT
3GR01169*DG
HOLMES COUNTY

Mr. Jim Rock
Holmes County Airport Authority
2 Court Street, Suite 21
Millersburg, OH 44654

Dear Mr. Rock:

On September 18, 2007 this writer conducted a compliance evaluation inspection of your facility located at 4501 Township road 307, Millersburg, Holmes County. The purpose of the inspection was to determine compliance with the above referenced General Stormwater NPDES permit. While you were not present, Jeff Miller was available and accompanied me during the site visit. Below in bullet form is a summary of the inspection:

- This is a very small low volume airport that does not operate in icing conditions. No deicing materials are used on the runways or the planes.
- There is one Jet fuel island. No containment or bin containing spill containment/cleanup materials was present. A picture was taken and is attached below.
- No maintenance is done in the individual hangers.
- All maintenance is done in the building located next to the office. In this building there exists one trench drain. A picture was taken and is attached below. It was not obvious to where the trench drain connected. Mr. Miller did not know where it discharged.
- Mr. Miller was unfamiliar with the stormwater program and was not able to show me your Stormwater Pollution Prevention Plan (SWPPP).

We request that the following items be addressed and information submitted to this office within 10 days of receipt of this letter:

- 1) A containment/cleanup bin should be located near the jet fuel island and be easily accessible should a spill occur. It should contain absorbent materials to be used in case of spillage of jet fuel.
- 2) Identify where the inside trench drain discharges.
- 3) Provide a copy of the SWPPP.

If you should have any questions, feel free to contact this writer at (330) 963-1136.


Sincerely,

Philip P. Rhodes
Environmental Engineer
Division of Surface Water

PPR/mlh

Attachments

Jet Fuel Island



Trench Drain

