



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

June 28, 2011

RE: MEDINA SUPPLY
3GR01050*DG
STORMWATER
SUMMIT COUNTY

Ms. Beth Mowrey
Shelly Materials
8775 Blackbird Lane
Thornville, Ohio 43076

Dear Ms. Mowrey:

On June 27, 2011 this writer conducted an inspection of your Medina Supply facility located at 1516 Highland Road, Twinsburg. The inspection was in response to a complaint received from Nicholas Fini, City Engineer, Village of Macedonia. The complaint alleged the discharge of excessive quantities of sand being discharged to the stream that runs through the Lake Forest Subdivision.

At the time of my inspection, there was no rain therefore I could not observe a storm event type situation. I focused on two areas of the site where stormwater is discharged. The first is the area located at the southwest corner of the property where the concrete trucks dump excess concrete coming back from the job site. The concrete is discharged onto the ground. It hardens with runoff directed through gravel filtration and finally ends up in a small pond equipped with a riser discharge pipe. Pictures are attached for reference. Inspection of the discharge from this pond, the drainage way on the north and south sides of the railroad tracks, and to another depressional area further downstream did not indicate the presence of sand or other evidence to suggest large quantities of sediment are leaving your site from the south end of the property. It is likely that a storm event of sufficient size could result in the eventual discharge of stormwater to the stream that travels through the subdivision. At this time it does not appear it would come from your site.

The sediment basin located on the north side of the property was also inspected. It was discharging at the time a clear effluent. No visual problems were noted. This outfall does not enter the drainage area that would enter the Lake Forest Subdivision. Pictures are attached. I will be re-inspecting the area downstream of your site during a storm event to reassess this issue in the near future.

On a side issue, it is our understanding that Shelly Materials now owns this site. Please be advised that the stormwater permit referenced above must be transferred to Shelly Materials. This should also be done for every other Medina Supply site bought by Shelly Materials. The permit is easily transferred by filling out a transfer form that can be found on our web site at:

Ms. Beth Mowrey
Medina Supply Company
June 28, 2011
Page 2

<http://www.epa.ohio.gov/dsw/storm/stormform.aspx>

If you should have any questions concerning this letter, feel free to contact this writer at (330) 963-1136 or by email phil.rhodes@epa.state.oh.us.

Sincerely,

A handwritten signature in black ink, appearing to read "Phil Rhodes". The signature is written in a cursive, flowing style.

Philip P. Rhodes, P.E.
Environmental Specialist II
Division of Surface Water

PPR/mt



