

**Environmental
Protection Agency**

OH7935812

Lamplighter Inn

11/30/2011

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director



November 30, 2011

LAMPLIGHTER INN
104 West Main Street
PORT WASHINGTON, OH 43837

Re: TUSCARAWAS COUNTY
LAMPLIGHTER INN
Transient Noncommunity Water System
PWS ID: OH7935812
STU ID: 7959304

DELINQUENCY NOTICE - ACTION REQUIRED

Subject: Failure to Monitor Drinking Water

LAMPLIGHTER INN is in violation of Ohio Administrative Code Rule 3745-81-23 for failing to monitor your drinking water during the June 1, 2011 to October 31, 2011 monitoring period and/or report results for the following contaminants: NITRITE (AS N).

LAMPLIGHTER INN must promptly take the following actions.

- A. If sample was taken during this monitoring period,**
 - a. Call your laboratory and have them submit the results to Ohio EPA.
 - b. Contact this office at (614) 644-2752 to consult with us on this issue.

- OR -
- B. If sample was not taken during or after this monitoring period,**
 - a. Immediately take a sample of your drinking water from the first tap following treatment.
 - b. Submit the sample for analysis to a certified laboratory on the enclosed list.

- OR -
- C. If sample was taken after this monitoring period,** contact this office at (614) 644-2752.

Your prompt attention to this matter is appreciated. Continued failure to sample during your scheduled time period may lead to enforcement which may include penalties. If you have questions, please call me at (614) 644-2752.

Sincerely,

Wendy Sheeran
Division of Drinking and Ground Waters

Enclosure: Laboratory List

cc: Superintendent/Manager; DDAGW-SEDO file; DDAGW-CO file

50 West Town Street, Suite 700
P.O. Box 1049
Columbus, Ohio 43216-1049

614 | 644 2752
614 | 644 2909 (fax)
www.epa.ohio.gov