



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

January 19, 2010

RE: COLLINS & AIKMAN
HOLMESVILLE
31100002 *ED
HOLMES COUNTY

Ms. Renee Barker
International Automotive Components Holmesville, LLC
8281 County Road 245
Holmesville, Ohio 44633

Dear Ms. Barker:

On January 13, 2010 this writer, along with Megan Talcott, DSW, NEDO conducted a compliance evaluation inspection of your facility to determine compliance with the above referenced NPDES permit. Collins & Aikman Automotive Mats is a manufacturer of auto floor mats and floor panels for the automotive industry.

Boiler blowdown, sanitary wastewater and water softener regeneration water (two on-site groundwater wells) is discharged to the Holmesville WWTP. Non-contact cooling water for 10 hydraulic presses is once thru and is sent to the fire pond located across the street. The fire pond overflows to the roadside ditch via outfall 001 which flows to Salt Creek to the South.

A review of your compliance history as determined by our SWIMS compliance tracking system for the time period of October 2006 through December 2009 did not indicate any numeric violations of your NPDES permit. However, upon review the record indicates that a monthly report was not submitted for July 2007. Please review your records to determine whether or not it was ever generated. If it was, resubmit it and inform the undersigned. If it was not submitted, then provide a written explanation by January 29, 2010.

We also reviewed your facility for compliance with the stormwater sections of your NPDES permit. A cursory review of your SWPPP generated the following comments:

- 1) The site plan should be updated to clearly document the location of all storm sewers, process, and sanitary sewers. For the storm sewers, clearly depict the location of all storm catch basins and the direction of flow.
- 2) Several open top dumpsters containing waste materials were observed on the north and south sides of the building. These locations must be clearly marked on your site plan.
- 3) The rest of the SWPPP appeared to adequately address all other requirements.

Pictures from the inspection are attached for your reference.

Ms. Renee Barker
International Automotive Components Holmesville, LLC
January 19, 2010
Page 2

If you should you have any questions concerning any of the above, feel free to contact this writer at (330) 963-1136.

Sincerely,

A handwritten signature in black ink, appearing to read "Phil Rhodes". The signature is fluid and cursive, with a large initial "P" and "R".

Philip P. Rhodes, P.E.
Environmental Specialist II
Division of Surface Water

PPR/mt

File: Industrial Permit/Compliance

IAC Holmesville 1/13/2010 open dumpster storage



IAC Holmesville view of loading dock
at NW corner of building 1/13/2010



