



State of Ohio Environmental Protection Agency

Northwest District Office

347 North Dunbridge Road
Bowling Green, OH 43402-9398

TELE: (419) 352-8461 FAX: (419) 352-8468
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

RE: Notice of Violation
Fulton County
Pleasant View Subdivision;
Ohio EPA Permit No. 2PG00109
NPDES Permit No. OH0122424
and
Airport Industrial Park
Ohio EPA Permit No. 2PG00110
NPDES Permit No. OH0122432

December 10, 2007

Mr. Leon L. Smith
Plant Operator
28 Willow Way
Archbold, OH 43502

Dear Mr. Smith:

We are in receipt of your self-monitoring reports covering the months of July 2007 through September 2007 for the referenced facilities. Our review indicates violations of the conditions of the NPDES permits. The specific instances of noncompliance are attached on separate sheets. Further review of your self-monitoring reports for the previous six months, ending in September 2007, for Airport Industrial Park indicates that you are in significant non-compliance (SNC) with an effluent limitation contained in your NPDES permit. The specific instance of SNC is attached on a separate sheet.

We have received your letters dated August 1, 2007, September 11, 2007, and October 3, 2007 for Pleasant View Subdivision and August 1, 2007 for Airport Industrial Park. No further response is needed regarding those violations.

Please be advised that failure to comply with the effluent limitations and/or monitoring requirements, including adequate laboratory controls, appropriate quality assurance procedures, and records retention, as specified in your Part III-General conditions of your NPDES permit may be cause for enforcement action pursuant to Ohio Revised Code, Chapter 6111. If these violations continue to occur and if satisfactory progress is not made, it may be necessary to initiate enforcement action to achieve compliance.

The Ohio EPA strongly encourages pollution prevention as the preferred approach for waste management. The first priority of pollution prevention is to eliminate the generation of wastes and pollutants at the source (source reduction). For those wastes or pollutants that are generated, the second priority is to recycle or reuse them in an environmentally sound manner. You can

Get New Data

Violations for Pleasant View Subdivision - July thru September 2007

| Permit No | Reporting Period | Station | Reporting Code | Parameter | Limit Type | Limit | Reported Value | Violation Date |
|-------------|------------------|---------|----------------|------------------|------------|-------|----------------|----------------|
| 2PG00109*BD | July 2007 | 001 | 00300 | Dissolved Oxygen | 1D Conc | 5.0 | 2.7 | 7/2/2007 |
| 2PG00109*BD | July 2007 | 001 | 00300 | Dissolved Oxygen | 1D Conc | 5.0 | 2.6 | 7/9/2007 |
| 2PG00109*BD | July 2007 | 001 | 00300 | Dissolved Oxygen | 1D Conc | 5.0 | 3.4 | 7/17/2007 |
| 2PG00109*BD | July 2007 | 001 | 00300 | Dissolved Oxygen | 1D Conc | 5.0 | 2.9 | 7/26/2007 |
| 2PG00109*BD | August 2007 | 001 | 00300 | Dissolved Oxygen | 1D Conc | 5.0 | 2.6 | 8/7/2007 |
| 2PG00109*BD | August 2007 | 001 | 00300 | Dissolved Oxygen | 1D Conc | 5.0 | 2.8 | 8/9/2007 |
| 2PG00109*BD | August 2007 | 001 | 00300 | Dissolved Oxygen | 1D Conc | 5.0 | 2.9 | 8/15/2007 |
| 2PG00109*BD | August 2007 | 001 | 00300 | Dissolved Oxygen | 1D Conc | 5.0 | 2.8 | 8/23/2007 |
| 2PG00109*BD | September 2007 | 001 | 00300 | Dissolved Oxygen | 1D Conc | 5.0 | 3. | 9/4/2007 |
| 2PG00109*BD | September 2007 | 001 | 00300 | Dissolved Oxygen | 1D Conc | 5.0 | 3.4 | 9/10/2007 |
| 2PG00109*BD | September 2007 | 001 | 00300 | Dissolved Oxygen | 1D Conc | 5.0 | 4.1 | 9/18/2007 |
| 2PG00109*BD | September 2007 | 001 | 00300 | Dissolved Oxygen | 1D Conc | 5.0 | 3.3 | 9/25/2007 |