



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

Re: Mercer County
M&R Eggs
IDP Inspection

April 21, 2011

Mr. Bill Glass, CEO
M&R Eggs
P. O. Box 307
Fort Recovery, Ohio 45846

Dear Mr. Glass:

This letter is to document our inspection of M & R Eggs in the Village of Fort Recovery on March 24, 2011. Please disregard our letter dated April, 6, 2011, as it was sent in error. Mr. Gary Parent was present and offered information about the facility and current operations.

The compliance schedule contained in the indirect discharge permit required you to submit a Permit to Install before January 1, 2007; however, to this date we have not received an application. Mr. Parent said that the facility has been working with Simpson Environmental Corporation and after two trial runs has decided on a pretreatment unit. This unit will be contained in a truck and has been very successful in decreasing the BOD load discharged from the facility. He stated that Mote and Associates are currently working on the Permit to Install.

We are in receipt of your self-monitoring reports covering the months of January 2010, through December 2010. Our review indicates violations of the conditions of the Indirect Discharge Permit. The specific violations are attached to this letter. In addition to the limit violations, there are also 116 frequency violations, which indicate that you are not properly sampling your discharge.

Please be advised that failure to comply with the compliance schedule effluent limitations and/or monitoring requirements may be cause for enforcement action pursuant to Ohio Revised Code, Chapter 6111. If these violations continue to occur and if satisfactory progress is not made, it may be necessary to initiate enforcement action to achieve compliance.

This inspection was conducted in conjunction with renewal of your Indirect Discharge Permit. We are currently drafting the permit and you should be receiving a draft soon. There is a 30 day comment period if you should have any comments about the conditions of the permit.

Mr. Bill Glass, CEO
April 21, 2011
Page 2

If you have any questions, please call me at (419) 373-3019.

Sincerely,



Michelle Sharp
Division of Surface Water

/llr

Enclosure

pc: ~~DSW-NWDO File - w/enclosures~~
Ryan Laake, DSW, CO - w/enclosures
Mr. Jeff Schwieterman - w/enclosures

Violation Date	Station	Reporting Code	Parameter	Limit Type	Limit	Reported Value
1/27/2010	001	80082	CBOD 5 day	1D Conc	910	4215.
2/23/2010	001	80082	CBOD 5 day	1D Conc	910	5385.
3/4/2010	001	00530	Total Suspended Solids	1D Conc	1150	3380.
3/4/2010	001	80082	CBOD 5 day	1D Conc	910	10425.
4/5/2010	001	80082	CBOD 5 day	1D Conc	910	1785.
4/5/2010	002	00530	Total Suspended Solids	1D Conc	750	2030.
4/5/2010	002	80082	CBOD 5 day	1D Conc	650	3830.
4/21/2010	002	00530	Total Suspended Solids	1D Conc	750	3400.
4/21/2010	002	80082	CBOD 5 day	1D Conc	650	2870.
4/28/2010	001	80082	CBOD 5 day	1D Conc	910	4416.
4/29/2010	002	80082	CBOD 5 day	1D Conc	650	4730.
5/6/2010	002	00530	Total Suspended Solids	1D Conc	750	1630.
5/6/2010	002	80082	CBOD 5 day	1D Conc	650	6100.
5/13/2010	002	00530	Total Suspended Solids	1D Conc	750	970.
5/13/2010	002	80082	CBOD 5 day	1D Conc	650	5530.
5/20/2010	002	00530	Total Suspended Solids	1D Conc	750	1320.
5/20/2010	002	80082	CBOD 5 day	1D Conc	650	4830.
5/26/2010	001	80082	CBOD 5 day	1D Conc	910	6795.
5/27/2010	002	00530	Total Suspended Solids	1D Conc	750	1060.
5/27/2010	002	80082	CBOD 5 day	1D Conc	650	4030.
6/3/2010	002	00530	Total Suspended Solids	1D Conc	750	3110.
6/3/2010	002	80082	CBOD 5 day	1D Conc	650	9100.
6/8/2010	001	00530	Total Suspended Solids	1D Conc	1150	1660.
6/8/2010	001	80082	CBOD 5 day	1D Conc	910	8115.
6/9/2010	002	00530	Total Suspended Solids	1D Conc	750	2680.
6/9/2010	002	80082	CBOD 5 day	1D Conc	650	7300.
6/17/2010	002	00530	Total Suspended Solids	1D Conc	750	860.
6/17/2010	002	80082	CBOD 5 day	1D Conc	650	4130.
6/24/2010	002	00530	Total Suspended Solids	1D Conc	750	2160.
6/24/2010	002	80082	CBOD 5 day	1D Conc	650	5530.
7/9/2010	001	00530	Total Suspended Solids	1D Conc	1150	1160.
7/9/2010	001	80082	CBOD 5 day	1D Conc	910	6435.
7/23/2010	001	00530	Total Suspended Solids	1D Conc	1150	21480.
7/23/2010	001	80082	CBOD 5 day	1D Conc	910	7155.
8/4/2010	001	80082	CBOD 5 day	1D Conc	910	1437.
8/4/2010	001	00402	pH, Minimum	1D Conc	5.0	4.14
8/26/2010	001	80082	CBOD 5 day	1D Conc	910	10485.
9/8/2010	001	00530	Total Suspended Solids	1D Conc	1150	1228.
9/8/2010	001	80082	CBOD 5 day	1D Conc	910	6150.
9/22/2010	001	00530	Total Suspended Solids	1D Conc	1150	1740.
9/22/2010	001	80082	CBOD 5 day	1D Conc	910	7275.
10/12/2010	001	00530	Total Suspended Solids	1D Conc	1150	1660.
10/12/2010	001	80082	CBOD 5 day	1D Conc	910	9015.
10/27/2010	001	00530	Total Suspended Solids	1D Conc	1150	1293.3
10/27/2010	001	80082	CBOD 5 day	1D Conc	910	7155.
11/3/2010	001	80082	CBOD 5 day	1D Conc	910	7725.
11/19/2010	001	80082	CBOD 5 day	1D Conc	910	3975.
12/9/2010	001	80082	CBOD 5 day	1D Conc	910	8280.
12/22/2010	001	00530	Total Suspended Solids	1D Conc	1150	2140.
12/22/2010	001	80082	CBOD 5 day	1D Conc	910	9915