

AKRON REGIONAL
AIR QUALITY MANAGEMENT DISTRICT

Agent of the Ohio Environmental Protection Agency - Division of the Akron Health Department
Serving Medina, Portage and Summit Counties

TELEPHONE: (330) 375-2480
FAX: (330) 375-2402

L. M. Malcolm, P.E.
Administrator

November 22, 2010

CERTIFIED MAIL

Mrs. Christine M. Williams, General Manager
Milich's Village Inn
4444 South Cleveland-Massillon Road
Norton, OH 44203

Dear Mrs. Williams:

RE: NOTICE OF VIOLATION

On Friday, November 19, 2010 I observed combustion of wax coated cardboard boxes in the outdoor incinerator of Milich's Village Inn. During operation of this incinerator it was discovered that the afterburner in the secondary chamber was not operable. Be advised that continued operation of your incinerator without secondary combustion by the afterburner may be in violation of Ohio Administrative Code (OAC) rules 3745-15-07(A), and/or 3745-19-03(B)(2)(b).

In order to operate your incinerator in compliance with applicable regulations, the emissions should be controlled by means of the afterburner. The afterburner should be operated each time waste is combusted in the incinerator.

The decision to pursue, or decline to pursue, enforcement action in this case will be made at a later date.

Keep in mind that this determination is based upon a site visit. It does not ensure that you have been or will continue to operate in compliance and in no way limits any liability if violations are discovered for this time period. If you have any questions, please contact me.

Sincerely,



Frederick J. Kramer
Air Quality Engineer

c: Mr. Frank Markunas, ARAQMD
Mr. Tom Kalman - Ohio EPA, DAPC
Complaint file C-286-10 ✓

CITICENTER - SUITE 904
146 SOUTH HIGH STREET • AKRON, OHIO 44308
An equal opportunity employer and provider of services - CRA 1964