



2GC0235020090603

WOOD DAVENPORT, HANF & CROCKER LLC 2GC02350 2009/06/03 TEBBE, PATRICIA PERRYSBURG



State of Ohio Environmental Protection Agency

Northwest District Office

347 North Dunbridge Rd.
Bowling Green, OH 43402-9398

TELE: (419) 352-8461 FAX: (419) 352-8468
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korfeski, Director

Re: Wood County
Davenport, Hanf & Crocker, LLC
Construction
Storm Water

June 3, 2009

Mr. Joel Nedrow
Rudolph Libbe
6494 Latcha Road
Walbridge, Ohio 43465

Dear Mr. Nedrow:

On May 28, 2009, I conducted an inspection of the Davenport, Hanf & Crocker LLC construction site located at 28300 Kensington Lane, Perrysburg, Ohio. The purpose of my visit was to evaluate compliance of the site with your National Pollutant Discharge Elimination System (NPDES) Permit for storm water associated with construction activity, Facility ID no. 2GC02350*AG (construction general permit or CGP). The inspection was conducted under the provisions of Ohio's water pollution control statutes, Ohio Revised Code (ORC) Chapter 6111.

At the time of the inspection, construction had begun, the site was cleared, graded and some stormwater sediment controls were in place.

The following are comments/violations from the inspection:

1. A construction entrance was installed but there was some off-site vehicle tracking of sediments and dust. Vehicles that enter and leave the construction site are to be restricted from muddy areas to minimize any off site tracking of sediment.
2. Silt fence had been erected along the stream bank. A few areas of the silt fence were not 16" above grade. Toward the back of the site the silt fence was installed on the slope of the bank rather than on the flattest area available; silt fence was not entrenched in areas; ends of the silt fence were not properly joined.

Mr. Joel Nedrow
June 3, 2009
Page 2

3. Areas of the stream bank that had been disturbed had generally been seeded and stabilized. However, there were some areas that had been redisturbed with dirt pushed down the bank.

Please send written notification of what corrective measures you have taken to correct the above violations. Please also submit all details for the design and construction of all post-construction controls for this site to my attention at this office within 10 days of the date on this letter. If you have any questions, you may contact me at (419) 373-3016 or by e-mail at patricia.tebbe@epa.state.oh.us.

Sincerely,



Patricia A. Tebbe, P.E.
Division of Surface Water

/lr

pc: ~~DSW/NWDO~~
City of Perrysburg