



Re: Auglaize County
Village of Cridersville
Community PWS
PWS ID# OH0600212
STU ID# 652910

April 28, 2011

Mr. John McDonald, Village Administrator
Village of Cridersville
110 West Main Street
Cridersville, Ohio 45806

Violation of the secondary standard for iron - NOV OAC 3745-82-02

Dear Mr. McDonald:

Notice of Violation

The Plant – Distribution Monthly Operation Report (EPA Form 5002) reported Iron greater than three-tenths milligrams per liter (mg/l) on March 24, 2011.

In violation of OAC 3745-82-02, the public water system has exceeded the secondary standard for iron which is 0.3 mg/L. There was one (1) week during the month in which iron exceeded the secondary standard.

Monitoring and compliance determinations for the secondary maximum contaminant level for iron are as follows:

- (a) Public water systems shall use the monitoring required by OAC 3745-83-01 (F)(5) to determine compliance with the secondary maximum contaminant level for iron.
- (b) A public water system shall be in violation of the secondary standard for iron when more than 25% of the monthly samples collected at each entry point to the distribution system exceed the secondary maximum contaminant level.

Violation of the secondary standard for iron does not require public notification. Please review your operations to determine the reason for the exceedance and advise this office as to what corrections will be made.

Mr. John McDonald, Village Administrator
April 28, 2011
Page 2

If you have any questions regarding this letter, or any other matter involving your water system, please feel free to contact me at 419-373-3101 or via e-mail to Chris.Riddle@epa.state.oh.us.

Sincerely,



Chris Riddle
Environmental Specialist 2
Division of Drinking and Ground Waters

/lr

pc: Auglaize County Health Department
DDAGW-NWDO File →